

AMACON

LIVE WELL

**Warranty Services
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 1010
Closing Date	1010 - 3515 Kariya
Date	0000
Contact Name(s)	19Dec08
Contact Telephone#	Jie Xin Lu
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
3732	✓ FOYER / ENTRY- WALLS-DRYWALL REPAIR WHERE NOTED PATCH/PAINT LEFT OF FRIDGE @ THE T OF WALL SEETAPE		✓	
3741	✓ LIVING/DINING ROOM- WINDOWS: 1-STRIP RIGHT OF PATIO DOOR NOT FLUSH WITH WALL GAP		✓	
3742	✓ LIVING/DINING ROOM- WINDOWS: 2-BLINDS MISSING		✓	
3744	✓ LIVING/DINING ROOM- WALLS-REPAINT DRYWALL & ABOVE ON CROWN MOULDING SEETAPE TELEPHONE JACK WALL		✓	
3745	✓ LIVING/DINING ROOM- WALLS: 1-REPAINT TOUCH UPS AROUND WINDOWS SEETAPE		✓	
3746	✓ MASTER BEDROOM- WALLS-DRYWALL REPAIR WHERE NOTED PATCH/PAINT LEFT OF VENT AT CEILING SEETAPE & TO THE RIGHT IN CORNER		✓	
3747	✓ MASTER BEDROOM- WALLS: 1-DRYWALL REPAIR WHERE NOTED PATCH/PAINT BELOW TELEPHONE JACK SEETAPE		✓	
3748	✓ MASTER BEDROOM- WALLS: 2-DENTED DRYWALL LEFT OF WINDOWS CABLE JACK WALL		✓	
3750	✓ MASTER BEDROOM- WALLS: 4-DRYWALL TOUCH UP ON WALL BELOW ELECTRIC PANEL		✓	
3755	✓ MASTER BEDROOM- CLOSET: 1-DRYWALL TOUCH UP SEETAPE 3 SPOTS		✓	
3757	✓ MASTER BEDROOM- CLOSET: 2-SCREWS POPPED RIGHT SIDE WHEN ENTERING SEE TAPE		✓	
3758	✓ MASTER BEDROOM- ELECTRICAL/LIGHTING-CABLE & TELEPHONE JACK WERE REQUESTED TO BE SWITCHED	Check customization sheet to see if homeowner has requested the re-location, if not advise them to contact the sales team	—	
3759	✓ MASTER BEDROOM- WINDOWS-BLINDS MISSING	Check customization sheet, blinds will be installed prior to occupancy	12/19/08	
3760	✓ MAIN BATHROOM- WALLS-PAINT TOUCH UPS RIGHT OF TILES AT TOWEL ROD 1 ABOVE 1 BELOW		✓	
3763	✓ MAIN BATHROOM- TUB-ALL AROUND TOP OF TILES BLACK MARKS CLEAN		✓	main bath
3767	✓ MAIN BATHROOM- CEILING-DRYWALL DENTED ABOVE DOOR SEETAPE & 1 FOOT BACK HAIR STUCK IN PAINT		✓	
3769	✓ MAIN BATHROOM- COUNTERTOPS-UNDER PLS SEE TAPE		✓	Kitchen's
3771	✓ MAIN BATHROOM- COUNTERTOPS: 1-FINISH SILICONE LEFT END OF COUNTER		✓	
3773	✓ MAIN BATHROOM- VANITY CABINETS-RIGHT DOOR CHIPPED 2 SPOTS ON RIGHT DOOR SEETAPE		✓	Kitchen's
3775	✓ MAIN BATHROOM- VANITY CABINETS: 1-CLEAN DOORS DIRTY		✓	
3776	✓ MAIN BATHROOM- FLOORING-NOT HAPPY WITH TILE WANT IT CHANGED TO MATCH ENTRY WAY		—	
3777	✓ MAIN BATHROOM- FLOORING-NOT HAPPY WITH TILE		—	

	WANT IT CHANGED TO MATCH ENTRY WAY			
3779	KITCHEN- CABINETS- CABINET DOOR RIGH UNDER SINK ADJUST			Kitchen's
3781	KITCHEN- CABINETS: 1-EXCESSIVE GAP BETWEEN CANBINET AND DISHWASHER PANEL SEE INSIDE RIGHT SIDE UNDER SINK			" "
3782	KITCHEN- CABINETS: 2-FACE PLATE MISSING ABOVE DISHWASHER MOUNTING???			" "
3784	KITCHEN- CABINETS: 3-CABINET RIGHTOF MICRWAVE SHELIVING NOT INSTALLED		✓	
3786	KITCHEN- CABINETS: 4-CABINET DOOR RIGHTOF & RIFGHT DOOR OF MICROWAVE BOTTOM HINGE NOT ATTACHED		✓	
3788	KITCHEN- CABINETS: 5-3RD CABINET TOP FROM FRIDGE SHEVES NOT INSTALLED		✓	
3790	KITCHEN- CABINETS: 6-BOTTOM DRAWER MISSING HANDLE			Kitchen's
3792	KITCHEN- CABINETS: 7-2ND & 3RD DRAWERS FROM TOP NEED ADJUSTING			" "
3794	KITCHEN- CABINETS: 8-BOTTOM COUPBOARD RIGHTOF DRAWERS SHELF NOT INSTALLED		✓	
3796	KITCHEN- CABINETS: 9-CABINET DOOR BOTTOM RIGHTOF DRAWERS ADJUST			" "

Date Completed: Dec 24/02

Amacon Customer Care Signature: [Signature]

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.