

LIVE WELL

# Warranty Services Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

|                           |   |
|---------------------------|---|
| <b>Location</b>           | <b>Eve - Tower: 1 - Unit: 1208</b><br><b>1208 - 3515 Kariya</b> |
| <b>Closing Date</b>       | 0000  |
| <b>Date</b>               | 13Feb09   |
| <b>Contact Name(s)</b>    | Matin Mazloun and Badi Abdolmaleki                              |
| <b>Contact Telephone#</b> |   |
| <b>Company:</b>           | Amacon Service  |
| <b>Attention:</b>         | Carlos Bravo  |
| <b>Telephone:</b>         |   |
| <b>Fax:</b>               | (905) 848-2827  |
| <b>From:</b>              | Warranty Services Department - Head Office                      |


| Please complete the following items: |  |  |                       |       |
|--------------------------------------|--|--|-----------------------|-------|
| Deficiency Number                    | Issue  |  | Appointment Date/Time | Notes |
| 10988 ✓                              | FOYER / ENTRY- WALLS-right small wall by mirror scratched -see tape  |  | ✓                     |       |
| 10989 ✓                              | FOYER / ENTRY- DOORS-doorframe scratched top and both sides -see tape  |  | ✓                     |       |
| 10990 ✓                              | FOYER / ENTRY- CLOSET-dpanel missing screw -see tape   |  | ✓                     |       |
| 10991 ✓                              | LIVING/DINING ROOM- ELECTRICAL/LIGHTING-fancoil missing filter -see tape   |  | ✓                     |       |
| 10993 ✓                              | LIVING/DINING ROOM- WINDOWS-alUMINUM frame scratched top left-see tape   |  | ✓                     |       |
| 10994 ✓                              | LIVING/DINING ROOM- WINDOWS: 1-alUMINUM casing scratched centre and left by slider -see tape                       |  | ✓                     |       |
| 10995 ✓                              | LIVING/DINING ROOM- WALLS-wall between bath and laundry closet below light switch patchy and black marks -see tape |  | ✓                     |       |
| 10996 ✓                              | LIVING/DINING ROOM- WALLS: 1-baseboard right wall chipped and bumpy -see tape                                      |  | ✓                     |       |
| 10997 ✓                              | MASTER BEDROOM- WALLS-yellow patch rightside of electrical panel -see tape   |  | ✓                     |       |

|         |   |  |   |  |
|---------|---|--|---|--|
| 10998 ✓ | MASTER BEDROOM- WALLS: 1-<br>black marks above fire alarm signal<br>panel -see tape |  | ✓ |  |
| 10999 ✓ | MASTER BEDROOM- WALLS: 2-<br>right wall black mark -see tape                        |  | ✓ |  |
| 11000 ✓ | MASTER BEDROOM- WALLS: 3-<br>hole in wall left of bulkhead by window<br>-see tape   |  | ✓ |  |
| 11001 ✓ | MASTER BEDROOM- CLOSET-<br>access panel in closet missing cover -<br>see tape       |  | ✓ |  |
| 11002 ✓ | MASTER BEDROOM- WINDOWS-<br>alUMINUM casing scratched leftside -<br>see tape        |  | ✓ |  |
| 11003 ✓ | MAIN BATHROOM- DOORS-<br>doorframe leading into bath chipped -<br>see tape          |  | ✓ |  |

Date Completed:

Feb 14/09 18

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back - Forms  
Menu

ID#  
10988/10989/10990/10991/10993/10994/10995/10996/10997/10998/10999/11000/11001/11002/11003  
Eve Ph 1 Lot 1208