

**AMACON**

LIVE WELL

**Warranty Services  
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

<b>Location</b>	<b>Eve - Tower: 1 - Unit: 1808</b> <b>1808 - 3515 Kariya</b>
<b>Closing Date</b>	0000
<b>Date</b>	13Feb09
<b>Contact Name(s)</b>	Maureen Lee Ah Yen and Edward Lee Ah Yen
<b>Contact Telephone#</b>	
<b>Company:</b>	Amacon Service
<b>Attention:</b>	Carlos Bravo
<b>Telephone:</b>	
<b>Fax:</b>	(905) 848-2827
<b>From:</b>	Warranty Services Department - Head Office


Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
11208 ✓	FOYER / ENTRY- WALLS-left wall on entering black marks and holes just above baseboard --see tape		✓	
11209 ✓	FOYER / ENTRY- DOORS- doorframe chipped top centre -see tape		✓	
11210 ✓	FOYER / ENTRY- DOORS: 1-excess caulking around doorframe -see tape		✓	
11211 ✓	LIVING/DINING ROOM- FLOORING-hall entry missing quarter round by left corner of mirror doors by kitchen gable -see tape		✓	
11216 ✓	LIVING/DINING ROOM- ELECTRICAL/LIGHTING-fancoil missing filter -see tape		✓	
11218 ✓	LIVING/DINING ROOM- WINDOWS-balcony doorframe missing ALUMINUM casing -see tape		✓	
11220	LIVING/DINING ROOM- WALLS-right wall several patcy marks -see tape		✓	Repaint Wall Right + Left sides
11221	LIVING/DINING ROOM- WALLS: 1-left wall several patchy spots -see tape		✓	
11222 ✓	MASTER BEDROOM- WALLS-dented wall by mirror doors see tape		✓	
11223	MASTER BEDROOM- CLOSET-		✓	

	access panel missing cover -see tape		✓	
11225 ✓	MASTER BEDROOM- WINDOWS- window lock needs to be screwed in - see tape		✓	
11226 ✓	MAIN BATHROOM- DOORS-door cracked by lock --see tape		✓	
11228 ✓	MAIN BATHROOM- TUB: 1- temperature control, faucet, showerhead need silicon -see tape		✓	
11237 ✓	LAUNDRY CLOSET- NOTE-dryer door not closing -see tape		✓	
11238 ✓	LAUNDRY CLOSET- DOORS-door chipped bottom left corner -see tape		✓	

Date Completed:

Feb 15/09 15

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

**Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

Back - Forms  
Menu

ID#

11208/11209/11210/11211/11216/11218/11220/11221/11222/11223/11225/11226/11228/11237/11238

Eve Ph 1 Lot 1808