

**AMACON**

LIVE WELL

**Warranty Services  
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

|                           |   |
|---------------------------|---|
| <b>Location</b>           | <u>Eve - Tower: 1 - Unit: 1908</u>                |
| <b>Closing Date</b>       | <u>1908 - 3515 Kariya</u>                         |
| <b>Date</b>               | <u>0000</u>                                       |
| <b>Contact Name(s)</b>    | <u>13Feb09</u>                                    |
| <b>Contact Telephone#</b> | <u>Grazyna Lozinski</u>                           |
| <b>Company:</b>           | <u>Amacon Service</u>                             |
| <b>Attention:</b>         | <u>Carlos Bravo</u>                               |
| <b>Telephone:</b>         |   |
| <b>Fax:</b>               | <u>(905) 848-2827</u>                             |
| <b>From:</b>              | <u>Warranty Services Department - Head Office</u> |

**Please complete the following items:**

| Deficiency Number | Issue  | Appointment Date/Time | Notes         |
|-------------------|--|-----------------------|---------------|
| 11271 ✓           | FOYER / ENTRY- WALLS-mark on left wall above door stop, see tape                       | ✓                     |               |
| 11272 ✓           | FOYER / ENTRY- DOORS-frame marked/scratched, see tape                                  | ✓                     |               |
| 11277             | LIVING/DINING ROOM- ELECTRICAL/LIGHTING-filter missing in fancoil                      | —                     | NO filter     |
| 11279 ✓           | LIVING/DINING ROOM- WINDOWS-panel to right of balcony door missing, see tape           | ✓                     |               |
| 11280 ✓           | LIVING/DINING ROOM- WINDOWS: 1-excessive caulking right side of balcony door, see tape | ✓                     |               |
| 11281 ✓           | LIVING/DINING ROOM- WINDOWS: 2-ALUMINUM THRESHOLD dented, see tape                     | —                     | allow Windows |
| 11282 ✓           | MASTER BEDROOM- WALLS-paint on J-mold left side and top of window                      | ✓                     |               |
| 11283 ✓           | MASTER BEDROOM- WALLS: 1-baseboard chipped 3 feet from window, left wall, see tape     | ✓                     |               |
| 11286 ✓           | MASTER BEDROOM- WINDOWS: 2-window sill higher on left side                             | —                     | metus         |
| 11287 ✓           | MASTER BEDROOM- WINDOWS: 3-paint on ALUMINUM frame, see tape                           | ✓                     |               |
| 11288 ✓           | DEN- CEILING-crack by air vent   | ✓                     |               |
| 11289 ✓           | MAIN BATHROOM- DOORS-lock not working  | ✓                     |               |
| 11290 ✓           | MAIN BATHROOM- DOORS: 1-door cracked at latch, see tape                                | ✓                     |               |
| 11291 ✓           | MAIN BATHROOM- TUB-silicone around showerhead, tap, faucet, see tape                   | ✓                     |               |
| 11295 ✓           | KITCHEN- CABINETS: 2-grout on underside of   | ✓                     |               |

|       |  |  |   |           |
|-------|--|--|---|-----------|
|       | uppercabinet to left of microwave, see tape                    |  |   |           |
| 11309 | KITCHEN- APPLIANCE-scratch on fridge door, see tape            |  | — | Whirlpool |
| 11310 | LAUNDRY CLOSET- NOTE-dryer door doesn't close properly         |  | — | " " " "   |
| 11311 | LAUNDRY CLOSET- NOTE: 1-water shut off too close to dryer      |  | ✓ |           |
| 11312 | LAUNDRY CLOSET- DOORS-handle hits dryer when shutting the door |  | ✓ |           |

Date Completed:

Feb 15/09 15

Amacon Customer Care Signature:

M. Fritz

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

**Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

Back -FormsMenu

ID#

11271/11272/11277/11279/11280/11281/11282/11283/11286/11287/11288/11289/11290/11291/11295/11309/11310/11311/11312

Eve Ph 1 Lot 1908