1508

## AMACON

LIVE WELL\*

## Warranty Services Work Order

Phone: (905) 848-2069 Fax:(905) 848-2827

Location Eve - Tower: 1 - Unit: 2008

2008 - 3515 Kariya

 Closing Date
 0000

 Date
 13Feb09

Contact Name(s) Eric Lap Ki Chan

Contact Telephone#

Company: Amacon Service
Attention: Carlos Bravo

Telephone:

Fax: (905) 848-2827

From: Warranty Services Department - Head Office

Please c	Please complete the following items:						
Deficiency Number	Issue		Appointment Date/Time	Notes			
11340	FOYER / ENTRY- DOORS-doorframe ha excess paint - see tape	/		·			
Ass	FOYER / ENTRY- DOORS: 1-large scratch bottom door see tape	X					
11343.	FOYER / ENTRY- DOORS: 2-markes on door see tape	X					
11349	LIVING/DINING ROOM- ELECTRICAL/LIGHTING-fancoil missing filter -see tape	X					
11350	LIVING/DINING ROOM- WINDOWS-balcony doorframe not finished - rightside by window metal showing -see tape	X		ALLAN WINDOWS			
11351	LIVING/DINING ROOM- WINDOWS: 1-alUMINUM casing bent and scratched -see tape	X		ALLAN WINDOWS  ALLAN WM DOWS  ALLAN weather stree  Pointers repaint			
11353	LIVING/DINING ROOM- WINDOWS: 2-balcony threshold cracked seal-see tape	X,		ALLAN weather stree			
11354	LIVING/DINING ROOM- WALLS-small left wall leading to master paint patchysee tape			, ,			
11355	LIVING/DINING ROOM- WALLS: 1-large left wall paint patchy -see tape	×		pomlas ve paint			
<sup>11356</sup> V	LIVING/DINING ROOM- WALLS: 2-right wall paint patchy - see tape						
11357 V	MASTER BEDROOM- DOORS-doorframe cracked - see tape	<b>V</b>					
11358	MASTER BEDROOM- DOORS: 1-doorframe chipped see tape						
11359 <b>V</b>	MASTER BEDROOM- DOORS: 2-door not staying closed						
11360 V	MASTER BEDROOM- FLOORING-carpets have stains -see tape						
11363	MASTER BEDROOM- ELECTRICAL/LIGHTING-light switch not flush -see tape	/					
11364 ل	DEN-ELECTRICAL/LIGHTING-cable outlet not flush -see tape	<b>V</b>					
11365	MAIN BATHROOM- TUB-temperature control, faucet and showerhead - need silicon -see tape	V					
11369	KITCHEN- COUNTERTOPS-kitchen island underneath silicon neededsee tape	X					
11371	KITCHEN- APPLIANCE-microwave light and fan unplugged	X		whirlpool light			

	for now stays on - see tape			
11372 i	KITCHEN- APPLIANCE: 1-fridge not plugged in -see tape			
11 1 /	KITCHEN- WALLS-bulkhead above microwave - both sides chippedsee tape	Į,V		

Date Completed: FFB 14 7009

Amacon Customer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -

**Forms** 

11340/11341/11343/11349/11350/11351/11353/11354/11355/11356/11357/11358/11359/11360/11363/11364/11365/11369/11371/11372/11373 **Menu** Eve Ph 1 Lot 2008