

**AMACON**

LIVE WELL

**Warranty Services  
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

<b>Location</b>	<u>Eve - Tower: 1 - Unit: 2105</u> <u>2105 - 3515 Kariya</u>
<b>Closing Date</b>	<u>0000</u>
<b>Date</b>	<u>19Jan09</u>
<b>Contact Name(s)</b>	<u>Mohammad Shiraz</u>
<b>Contact Telephone#</b>	
<b>Company:</b>	<u>Amacon Service</u>
<b>Attention:</b>	<u>Carlos Bravo</u>
<b>Telephone:</b>	
<b>Fax:</b>	<u>(905) 848-2827</u>
<b>From:</b>	<u>Warranty Services Department - Head Office</u>

**Please complete the following items:**


Deficiency Number	Issue		Appointment Date/Time	Notes
6474	FOYER / ENTRY- DOORS-marks on right side of door frame where taped		✓	
6476	LIVING/DINING ROOM- WALLS-mark to right of thermostat		✓	
6477	LIVING/DINING ROOM- WALLS: 1-mark on wall flanking kitchen where taped		✓	
6478	GUEST BEDROOM 1- WALLS-mark left wall adjacent to window by outlet where taped		✓	
6479	GUEST BEDROOM 1- WALLS: 1-mark on right wall above telephone jack where taped		✓	
6480	GUEST BEDROOM 1- WINDOWS-ALUMINUM marked above sliding window where taped		✓	
6481	MASTER BEDROOM- WALLS-mark corner wall across from fan coil unit		✓	
6482	MASTER BEDROOM- WALLS: 1-marks on right wall adjacent to window		✓	
6483	MAIN BATHROOM- DOORS-chip in door casing left side interior above hinge see tape		✓	
6485	MAIN BATHROOM- VANITY			

	CABINETS-repair drawer pull		✓	
6487	ENSUITE BATHROOM- DOORS-lock does not work		✓	
7274	KITCHEN- CABINETS-excessive gap lazy susan cupboard		✓	

Date Completed:

Jan 20/09

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

**Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

[Back - Forms Menu](#)

ID# 6474/6476/6477/6478/6479/6480/6481/6482/6483/6485/6487/7274 Eve Ph 1 Lot 2105