AMACON

Warranty Services Work Order

LIVE WELL

Phone: (905) 848-2069 Fax:(905) 848-2827

Location Eve - Tower: 1 - Unit: 2203

2203 - 3515 Kariya

Closing Date Date 0000 29Jan09

Contact Name(s)

Dorcas Wah

Contact Telephone#

Company:

Amacon Service

Attention: Telephone:

Carlos Bravo

Fax:

(905) 848-2827

From:

Warranty Services Department - Head Office

Please complete the following items:					
Deficiency Issue Number	Appointment Notes Date/Time				
FOYER / ENTRY- WALLS-paint/drywall discolored above entry door, see tape	Date Fine				
FOYER / ENTRY- WALLS: 1-paint cracked along left side of entry door, see tape					
FOYER / ENTRY- CEILING-AIR HOLES/marks on ceiling					
FOYER / ENTRY- CLOSET-mechanical access panel not flush, see tape					
POSSET / ENTRY- CLOSET: 1-gap right end of valance, see tape	1 September 1				
LIVING/DINING ROOM- ELECTRICAL/LIGHTING-fan coil access cover dented/not closing, see tape					
MASTER BEDROOM- WALLS-marks on drywall beside closet, see tape					
MASTER BEDROOM- WALLS: 1-marks on drywall beside left window, see tape					
MASTER BEDROOM- CEILING-3 HOLES near canopy cover	- Mark.				
MASTER BEDROOM- ELECTRICAL/LIGHTING-outlets not flush, see tape					
MASTER BEDROOM- WINDOWS-marks/gaps along j-mold, see tape	* percent				
DEN- FLOORING-excess gaps where taped	in the work				
DEN- CEILING-AIR HOLES/marks on ceiling	was the track				
DEN- ELECTRICAL/LIGHTING-outlets not flush, see tape					
DEN- ELECTRICAL/LIGHTING: 1-air vent not					

	flush, see tape		
9570	MAIN BATHROOM- WALLS-marks on drywall, see tape		
9571 /	MAIN BATHROOM- DOORS-scratch on outside door handle	Lander	
9572 /	MAIN BATHROOM- TUB-silicone around showerhead, tap, overflow, see tape	 Land and the same of the same	4
9573	MAIN BATHROOM- TUB: 1-silicone cracked along top edge of tub, see tape	Land	
9574 /	MAIN BATHROOM- TUB: 2-'bump' above overflow, see tape	 1 de	aži.
9575 /	MAIN BATHROOM- VANITY CABINETS- realign vanity cabinet doors	 Lander	
9576	KITCHEN- CABINETS-realign drawers		HT.L.
9577	KITCHEN- CABINETS: 1-please paint access panel inside lazy susan cupboard	 Landard	

Date Completed: Jan 34/04 | Amacon Customer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827. Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and

all repairs. All costs incurred will be applied to the Company listed above.

Back -

Forms

ID#

9554/9555/9556/9557/9558/9560/9561/9562/9563/9564/9565/9566/9567/9568/9569/9570/9571/9572/9573/9574/9575/9576/9577 Eve Ph 1 Lot 2203