

A M A C O N

L I V E W E L L ®

Warranty Services**Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 2205
Closing Date	2205 - 3515 Kariya
Date	0000
Contact Name(s)	22Jan09
Contact Telephone#	Manal Abdalla
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
7965	✓ FOYER / ENTRY- DOORS-doorframe scratched by right side see tape		✓	
7966	✓ LIVING/DINING ROOM- WALLS-left wall by kitchen entry - paint touchup needed see tape		✓	
7967	✓ LIVING/DINING ROOM- WALLS: 1-left wall above outlet large dent -- see tape		✓	
7968	✓ LIVING/DINING ROOM- WALLS: 2-left wall by large window 2in above baseboard dented see tape		✓	
7969	✓ LIVING/DINING ROOM- WALLS: 3-left wall corner entering kitchen -- paint touchups needed		✓	
7970	✓ GUEST BEDROOM 1- WALLS-right wall by closet door 1ft from baseboard black marks -- see tape		✓	
7971	✓ GUEST BEDROOM 1- FLOORING-carpet stain - several spots see tap		✓	
7973	✓ GUEST BEDROOM 1- CLOSET-guest bedroom closet door need adjusting - see tape		✓	
7974	✓ GUEST BEDROOM 1- WINDOWS-window frame scratched -- see tape		✓	
7975	✓ DEN- WALLS-centre wall by ceiling of den black mark - see tape		✓	
7976	✓ DEN- WALLS: 1-right wall of den - 2ft from floor paint touchup needed		✓	
7977	✓ DEN- WALLS: 2-left wall of den -- small dents see tape		✓	
7979	✓ MAIN BATHROOM- WALLS-right wall by toilet dented -see tape		✓	
7980	✓ MAIN BATHROOM- WALLS: 1-right wall by toilet paint touchups needed see tape		✓	
7981	✓ MAIN BATHROOM- DOORS-entry doorframe to main bathroom cracked by wall - right side see tape		✓	
7982	✓ ENSUITE BATHROOM- ELECTRICAL/LIGHTING-		✓	

	2 bulbs burnt out see tape		✓	electrical light (mark)
7983	ENSUITE BATHROOM- ELECTRICAL/LIGHTING: 1-vent switch backward -- need to be flipped see tape		✓	
7985	KITCHEN- CEILING-ceiling by kitchen window -- spots on ceiling -- see tape		✓	
7986	KITCHEN- CEILING: 1-ceiling above dishwasher bulkhead scratched -- see tape		✓	
7987	KITCHEN- WINDOWS-kitchen window j mould needs touchup		✓	
7988	KITCHEN- BACKSPLASH-grout needed right edge of stove -- see tape		✓	
7989	KITCHEN- WALLS-wall above microwave needs touchup see tape		✓	
7990	KITCHEN- WALLS: 1-right edge by balcony door black marks on wall see tape		✓	
7991	KITCHEN- DOORS-balcony door in kitchen top edge scratched -- see tape		✓	

Date Completed: Jan 23/07

Amacon Customer Care Signature: *[Signature]*

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.
Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -
Forms
Menu

ID#

7965/7966/7967/7968/7969/7970/7971/7973/7974/7975/7976/7977/7979/7980/7981/7982/7983/7985/7986/7987/7988/7989/7990/7991

Eve Ph 1 Lot 2205