

AMACON

LIVE WELL

**Warranty Services
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 2209 2209 - 3515 Kariya
Closing Date	0000
Date	22Jan09
Contact Name(s)	Tony Visconti
Contact Telephone#	
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:


Deficiency Number	Issue	Appointment Date/Time	Notes
7532	FOYER / ENTRY- DOORS-left doorframe by lock - paint chipped see tape	✓	
7533	FOYER / ENTRY- DOORS: 1-drywall chipped left corner above doorframe - see tape	✓	
7538	LIVING/DINING ROOM- FLOORING: 2-quarter round left corner edge by main bathroom chipped - see tape	✓	
7540	LIVING/DINING ROOM- ELECTRICAL/LIGHTING-fancoil in way - customer would like moved to inside the den- in way of tv - see tape	✓	Can't be moved
7541	LIVING/DINING ROOM- WINDOWS-window casing by den chipped - see tape	✓	
7542	LIVING/DINING ROOM- WALLS-top left corner of balcony doorframe scratched - see tape	✓	
7543	GUEST BEDROOM 1- DOORS-inside and outside door handles to guest bedroom scratched	✓	NEW HANDLE
7544	GUEST BEDROOM 1- CLOSET-ADJUST TRACK seems to be bent see tape	✓	OK
7545	MASTER BEDROOM- WALLS-edges between windows scratched see tape	✓	
7546	MAIN BATHROOM- WALLS-doorframe right edge paint is bubbled - see tape	✓	
7547	MASTER BEDROOM- DOORS-door cracked by lock see tape	✓	
7548	MAIN BATHROOM- VANITY CABINETS-top doors of vanity cabinet not aligned	✓	
7550	MAIN BATHROOM- ELECTRICAL/LIGHTING-lighting fixture - 3 light shade not straight	✓	
7551	ENSUITE BATHROOM- DOORS-door not locking when closed - see tape	✓	OK
7553	ENSUITE BATHROOM- VANITY CABINETS-cabinet doors need adjusting see tape	✓	
7555	KITCHEN- --bulkhead above pantry paint touchups needed	✓	
7556	KITCHEN- FLOORING-quarter round not painted by island see tape	✓	
7557	KITCHEN- CABINETS-pantry cabinets double doors not aligned	✓	
7560	KITCHEN- CABINETS: 1-cabinet door above microwave needs to be adjusted see tape	✓	
7562	KITCHEN- CABINETS: 3-second upper cabinet right of fridge laminate bottom edge scratched see tape	✓	Kitchen's
7564	KITCHEN- CABINETS: 4-screw showing bottom left corner left of stove see tape	✓	
7566	KITCHEN- CABINETS: 7-drawers right of fridge not aligned - see tape	✓	
7568	KITCHEN- APPLIANCE-fridge door scratched see tape	✓	Whirlpool
7569	KITCHEN- APPLIANCE: 1-appliances not plugged in - all	✓	
7570	KITCHEN- APPLIANCE: 2-stove top scratched - large right burner	✓	Whirlpool
7571	LAUNDRY CLOSET- --washer and dryer need to be moved- cannot open doors	✓	

7572	LAUNDRY CLOSET- DOORS-t-cap on sliding mirror door right bottom corner missing screws			
7608	DEN- WALLS-Jmould left side -- upper of window needs paint touchup			
7609	MAIN BATHROOM- FLOORING-grout not even between tiles see tape			

Date Completed:

Jan 27/09/18

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -FormsMenu

ID#

7532/7533/7538/7540/7541/7542/7543/7544/7545/7546/7547/7548/7550/7551/7553/7555/7556/7557/7560/7562/7564/7566/7568/7569/7570/7571/7572/7608/7609

Eve Ph 1 Lot 2209