

**AMACON**

LIVE WELL™

**Warranty Services  
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

|                           |   |
|---------------------------|---|
| <b>Location</b>           | <u>Eve - Tower: 1 - Unit: 2503</u><br><u>2503 - 3515 Kariya</u> |
| <b>Closing Date</b>       | <u>0000</u>   |
| <b>Date</b>               | <u>23Jan09</u>  |
| <b>Contact Name(s)</b>    | <u>Roya Wafa</u>  |
| <b>Contact Telephone#</b> |   |
| <b>Company:</b>           | <u>Amacon Service</u>   |
| <b>Attention:</b>         | <u>Carlos Bravo</u>   |
| <b>Telephone:</b>         |   |
| <b>Fax:</b>               | <u>(905) 848-2827</u>   |
| <b>From:</b>              | <u>Warranty Services Department - Head Office</u>               |

**Please complete the following items:**


| Deficiency Number | Issue   |  | Appointment Date/Time | Notes                              |
|-------------------|---|--|-----------------------|------------------------------------|
| 8230 ✓            | FOYER / ENTRY- CLOSET-De-mark Panel needs to be painted                                     |  | ✓                     |                                    |
| 8231 ✓            | LIVING/DINING ROOM- FLOORING-patio door sill is not straight and has a gap on the left side |  | ✓                     | filling up gap!                    |
| 8232 ✓            | LIVING/DINING ROOM- WALLS- dent and scratch left of patio door frame                        |  | -                     | fixed scratches<br>Kallan Williams |
| 8233 ✓            | MASTER BEDROOM- WALLS-rough finish around alarm button                                      |  | •                     |                                    |
| 8234 ✓            | MASTER BEDROOM- WALLS: 1-outlet next to tel jack not flush with the wall                    |  | ✓                     |                                    |
| 8235 ✓            | MASTER BEDROOM- CLOSET- bumbars missing and chips on edges of doors                         |  | ✓                     |                                    |
| 8236 ✓            | MASTER BEDROOM- WINDOWS- frames need cleaning   |  | ✓                     |                                    |
| 8237 ✓            | MAIN BATHROOM- DOORS-lock not working   |  | ✓                     |                                    |
| 8238 ✓            | MAIN BATHROOM- TUB-need to silicon around shower pipe cover                                 |  | ✓                     |                                    |
| 8239 ✓            | MAIN BATHROOM- TOILET-pip cover needs to be fixed to the wall                               |  | ✓                     |                                    |
| 8242              | KITCHEN- CABINETS: 1-filler piece   |  | ✓                     |                                    |

|      |   |   |  |   |  |
|------|---|---|--|---|--|
|      | ✓ | right of stove needs cleaning   |  | ✓ |  |
| 8245 | ✓ | KITCHEN- CABINETS: 4-back gable missing silicon and seams not straight        |  | ✓ |  |
| 8246 | ✓ | KITCHEN- SINK-veggie spray does not move smoothly                             |  | ✓ |  |
| 8247 | ✓ | KITCHEN- APPLIANCE-black mark in back of m/w                                  |  | ✓ |  |
| 8248 | ✓ | KITCHEN- APPLIANCE: 1-dishwasher will not close becuse of screw on right side |  | ✓ |  |
| 8249 | ✓ | LAUNDRY CLOSET- WALLS-gap under water shut-off                                |  |   |  |

Date Completed:

Jan 24/09

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

**Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

[Back - Forms Menu](#)

ID# 8230/8231/8232/8233/8234/8235/8236/8237/8238/8239/8242/8245/8246/8247/8248/8249

Eve Ph 1 Lot 2503