

A M A C O N

L I V E W E L L

**Warranty Services
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	<u>Eve - Tower: 1 - Unit: 2510</u> <u>2510 - 3515 Kariya</u>
Closing Date	<u>0000</u>
Date	<u>28Jan09</u>
Contact Name(s)	<u>Keith Simpson</u>
Contact Telephone#	
Company:	<u>Amacon Service</u>
Attention:	<u>Carlos Bravo</u>
Telephone:	
Fax:	<u>(905) 848-2827</u>
From:	<u>Warranty Services Department - Head Office</u>


Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
7108	FOYER / ENTRY- WALLS-marks and dents in drywall opposite entry door where taped	✓		
7109	FOYER / ENTRY- WALLS: 1-DRYWALL cracked at bulkhead right of entry door where taped	✓		
7110	FOYER / ENTRY- CLOSET-scratch on aluminum track above closet doors	✓		
7129	LIVING/DINING ROOM- WINDOWS: 1-ALUMINUM marked/scratched around balcony door where taped	✓		
7130	LIVING/DINING ROOM- WALLS-hole in drywall left wall under outlet where taped	✓		
7131	LIVING/DINING ROOM- WALLS: 1-divot in drywall left wall 6 inches below ceiling where taped	✓		
7132	LIVING/DINING ROOM- WALLS: 2-DRYWALL DENTED left wall adjacent to bedroom where taped	✓		
7133	MASTER BEDROOM- WALLS-DRYWALL rough by fire alarm silencer	✓		
7134	MASTER BEDROOM- WALLS: 1-DRYWALL rough right wall where taped	✓		
7135	MASTER BEDROOM- WALLS: 2-DRYWALL DENTED underside of bulkhead by windows	✓		
7136	MASTER BEDROOM- WALLS: 3-excessive caulking left wall at the window	✓		
7137	MASTER BEDROOM- WALLS: 4-marks/dents on drywall left wall where taped	✓		
7138	MASTER BEDROOM- FLOORING-BASEBOARD BROKEN right wall where taped	✓		
7139	MASTER BEDROOM- FLOORING: 1-CLEAN CARPET	✓		
7140	MAIN BATHROOM- WALLS-drywall rough along left side of tub where taped	✓		
7141	MAIN BATHROOM- WALLS: 1-DRYWALL rough right wall where taped	✓		
7142	MAIN BATHROOM- DOORS-mark inside door below door handle where taped	✓		

7143	MAIN BATHROOM- CEILING-dent by exhaust fan where taped	✓		
7144	MAIN BATHROOM- CEILING: 1-excessive plaster on ceiling where taped	✓		
7149	KITCHEN- COUNTERTOPS-excessive gap underside of island countertop facing living room	✓		
7151	KITCHEN- WALLS-drywall rough/ruled left wall where taped	✓		
7152	KITCHEN- WALLS: 1-mark to right of fridge where taped	✓		
7153	LAUNDRY CLOSET- NOTE-please shut secondary lint trap door	✓		
7154	LAUNDRY CLOSET- DOORS-chips in door frame where taped	✓		
7294	LIVING/DINING ROOM- WINDOWS: 1-ALUMINUM marked/scratched around balcony door where taped	✓		

Date Completed:

JANUARY 30, 09

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -
Forms
Menu

ID#

7108/7109/7110/7129/7130/7131/7132/7133/7134/7135/7136/7137/7138/7139/7140/7141/7142/7143/7144/7149/7151/7152/7153/7154/7294
 Eve Ph 1 Lot 2510