

AMACON

LIVE WELL


**Warranty Services
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

| | |
|---------------------------|---|
| Location | <u>Eve - Tower: 1 - Unit: 2703</u> <u>2703 - 3515 Kariya</u> |
| Closing Date | <u>0000</u> |
| Date | <u>02Feb09</u> |
| Contact Name(s) | <u>Anthony Au and Nga Kwan Lee</u> |
| Contact Telephone# | |
| Company: | <u>Amacon Service</u> |
| Attention: | <u>Carlos Bravo</u> |
| Telephone: | |
| Fax: | <u>(905) 848-2827</u> |
| From: | <u>Warranty Services Department - Head Office</u> |

| Please complete the following items: | | | | |
|--------------------------------------|---|---|-----------------------|--------------|
| Deficiency Number | Issue | | Appointment Date/Time | Notes |
| 9684 | FOYER / ENTRY- WALLS-crack rightside above doorframe - see tape | ✓ | | |
| 9685 | FOYER / ENTRY- WALLS: 1-rightsie of mirror closet door baseboard chipped see tape | ✓ | | |
| 9686 | FOYER / ENTRY- DOORS-doorframe by lock scratched - see tape | ✓ | | |
| 9687 | FOYER / ENTRY- DOORS: 1-doorframe top left edge scratched - see tape | ✓ | | |
| 9692 | LIVING/DINING ROOM- WALLS-entry to balcony steps not aligned | ✓ | | CALL METRO |
| 9694 | LIVING/DINING ROOM- WALLS: 1-doorframe touchups needed - caulking messy -- see tape | ✓ | | |
| 9695 | LIVING/DINING ROOM- WALLS: 2-left wall baseboard by outlet dented to spots -- see tape | ✓ | | |
| 9696 | MASTER BEDROOM- WALLS-large scratch rightside of outlet - 6in above baseboard -- see tape | ✓ | | |
| 9697 | MASTER BEDROOM- DOORS-large gap by doorframe when door closed -- see tape | ✓ | | |
| 9698 | MASTER BEDROOM- DOORS: 1-doorframe leftside paint touchups needed | ✓ | | |
| 9699 | MASTER BEDROOM- DOORS: 2-inside doorframe large crack by wall -- see tape | ✓ | | |
| 9701 | MASTER BEDROOM- FLOORING: 1-baseboard bottom left edge by mirror doors chipped - see tape | ✓ | | |
| 9702 | MASTER BEDROOM- CEILING-rightsie by window mould is dirty - see tape | ✓ | | |
| 9703 | MASTER BEDROOM- CLOSET-mirror closet doors edges scratched - see tape | ✓ | | |
| 9704 | MASTER BEDROOM- WINDOWS-window frame scratched several spots see tape | ✓ | | |
| 9705 | DEN- WALLS-right wall -- 2ft from light switch bump in paint | ✓ | | |
| 9708 | MAIN BATHROOM- DOORS-door not locking | ✓ | | |
| 9709 | MAIN BATHROOM- TUB-faucet and spout not sealed -- see tape | ✓ | | |
| 9710 | MAIN BATHROOM- SINK-sink not sealed properly -- small hole | ✓ | | |
| 9712 | MAIN BATHROOM- ELECTRICAL/LIGHTING-light bulb burnt out see tape | ✓ | | |
| 9713 | KITCHEN- FLOORING-quarter round by livingroom dented see tape | | | CALL SALWOOD |
| 9717 | KITCHEN- SINK-not sealed -- need silicon -- see tape | ✓ | | C |

| | | | | |
|------|---|---|--|--|
| 9718 | KITCHEN- APPLIANCE-microwave not plugged in | ✓ | | |
| 9719 | KITCHEN- APPLIANCE: 1-dishwasher not plugged in | ✓ | | |
| 9720 | KITCHEN- WALLS-island gable leftside 1/4 gap see tape | ✓ | | |
| 9721 | LAUNDRY CLOSET- DOORS-not staying shut see tape | ✓ | | |
| 9722 | KITCHEN- WALLS: 1-kitchen island underneath not attached - see tape | ✓ | | |

Date Completed: FEBRUARY 2, 09Amacon Customer Care Signature: 

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -

Forms

Menu

ID#

9684/9685/9686/9687/9692/9694/9695/9696/9697/9698/9699/9701/9702/9703/9704/9705/9708/9709/9710/9712/9713/9717/9718/9719/9720/9721/9722
Eve Ph 1 Lot 2703