AMACON

LIVE WELL

Warranty Services Work Order Phone: (905) 848-2069 Fax:(905) 848-2827

Location	Eve - Tower: 1 - Unit: 2705
	2705 - 3515 Kariya
Closing Date	0000
Date	02Feb09
Contact Name(s)	Harinder Sandhu
Contact Telephone#	
Company:	Amacon Service
Attention:	Carlos Brayo
Telephone:	and a distriction.
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:				
Deficiency Issup			ment Notes	
Number		Date/Time	1 1000	
8543 OYER / ENTRY- WALLS-right side by light switch 2 dents see tape				
8544 OYER / ENTRY- WALLS: 1-right bulkhead by main bathroom dented see tape				
8545 OYER / ENTRY- CEILING-stiple has black marks in entry left corner when looking at entry door				
8551 VIVING/DINING ROOM-ELECTRICAL/LIGHTING-paint spots on fancoil - see tape				
8552 / LIVING/DINING ROOM- ELECTRICAL/LIGHTING: 1-paint on outtake grate see tape	√			
8553 / LIVING/DINING ROOM- CEILING-black marks on ceiling stiple edges by window black marks pheck entire ceiling				
8554 / IVIVING/DINING ROOM- CEILING: 1-centre wall by master entry large hole	1			
8555 LIVING/DINING ROOM- CEILING: 2-ceiling by entry large crack — see tape				
8556 VIVING/DINING ROOM- WALLS-right side baseboard chipped two spots see tape	7	 		
8557 LIVING/DINING ROOM- WALLS: 1-right edge by fancoil and window edges rough — see tape	1			
8558, LIVING/DINING ROOM- WALLS: 2-far left corner edge 3ft from floor dented - see tape	V.			
8559 VIVING/DINING ROOM- WALLS: 3-right edge by kitchen entry paint touchups needed	-			
8560 VIVING/DINING ROOM- WALLS: 4-left wall by kitchen entry several dents in walls see tape	Ż			
8561 LIVING/DINING ROOM- WALLS: 5-right wall - right of fancoil nailpop see tape	.,	 		
8562 LIVING/DINING ROOM- WALLS: 6-right wall above outlet several dents in wall see tape	V			
8563 VIVING/DINING ROOM- WALLS: 7-above thermostat dents in wall see tape	Ž			
8564 V LIVING/DINING ROOM- WALLS: 8-right wall by master bedroom entry - right of outlet wall joint showing	- /			
	Ŭ.			
8565 LIVING/DINING ROOM- WALLS: 9-right wall by master bedroom entry several dents in wall see tape				
8566 / LIVING/DINING ROOM- WALLS: 10-centre wall below light switch dented see tape	7			
8567 GUEST BEDROOM 1- WALLS-right on entering by telephone jack wall to be sanded see tape	V			
8568 GUEST BEDROOM 1- WALLS: 1-below cable jack walls dented see tape	1			
8569 / CUEST BEDROOM 1- WALLS: 2-left edge by window dented see tape				
8570 GUEST BEDROOM 1- CEILING-black marks ceiling by wall edges				
8571 ØUEST BEDROOM 1- CLOSET-right edge of closet dented see tape				
MASTER BEDROOM- WALLS-dentes in wall left of fancoil see tape				
8573 MASTER BEDROOM- WALLS: 1-right wall in master bedroom nook several dents see tape	√			
8574 MASTER BEDROOM- WALLS: 2-centre wall in master bedroom nook dented see tape	Ţ			
8575 / MASTER BEDROOM- WALLS: 3-right wall upon entering dented several spots - see tape				
8576 / MASTER BEDROOM- WALLS: 4-right wall bulkhead below grate dented see tape	V			
8577 / MASTER BEDROOM- WALLS: 5-right wall by outlet dented see tape	·./			
8578 MASTER BEDROOM- WALLS: 6-right wall above electrical panel - dent	<u>~</u>			
8579 MASTER BEDROOM- WALLS: 7-left wall by telephone jack nedds sanded see tape	7	7-		
8580 MASTER BEDROOM- DOORS-doorframe cracked frame left top corner	V			
8581 MASTER BEDROOM- CEILING-ceiling black marks several spots	-			
MASTER BEDROOM- CEILING: 1-entry to ensuite ceiling has black marks by edges in stiple	~			
8584 DEN- WALLS-right side of guest bedroom dent by light switch see tape	Ž.			
8585 ZEN- FLOORING-2 scratches by centre wall see tape				
8586 /MAIN BATHROOM- WALLS-right wall by toilet dented see tape	1			
ENSUITE BATHROOM- WALLS-left edge above miirror walls need to be sanded - see tape	- ₹/			
8589 / ENSUITE BATHROOM- WALLS: 1-right side toilet walls dented see tape	V			
2590 ENSUITE BATHROOM- WALLS: 2-right side of sink below outlet walss need to be sanded see tape	V			
KITCHEN- CABINETS-upper cabinet right of fridge bandle loose				
S599 KITCHEN- WALLS: 1-left edge by large window 2ft from floor walls dented				
KITCHEN- WALLS: 2-bulkhead above fridge dented see tape				
KITCHEN- WALLS: 3-left edge by balcony wall edge dented	J			
	<u> </u>			

8602 KITCHEN- WALLS: 4-bulkhead above microwave wall dented see tape	
Date Completed: Followy 3,09	Amacon Customer Care Signature:
Please schedule your Service Department to complete work on the above Unit. Should no appointment time cappointment you have scheduled. Your service representative must have this form signed by homeowner on Failure to comply with this request will give Amacon Developments (and it's group of companies) the rabove.	