

Warranty Services Work Order

LIVE WELL Phone: (905) 848-2069 Fax: (905) 848-2827

Location	<u>Eve - 10wer: 1 - Onn: 2910</u>	
	<u> 2910 - 3515 Kariya</u>	
Closing Date	0000	
Date	09Feb09	
Contact Name(s)	Randall Davis and Gracilyn Davis	
Contact Telephone#		
Company:	Amacon Service	

Attention: Carlos Bravo

Telephone:

(905) 848-2827 Fax:

Warranty Services Department - Head Office From:

Please o	complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes	
9363	FOYER / ENTRY- WALLS-rightside of mirror closet door chipped paint-see tape	- Group Assign			
9364	FOYER / ENTRY- WALLS: 1-wall facing entry black marks see tape	- Group Assign			
9365 \	FOYER / ENTRY- DOORS-doorframe seratched - top and sides see tape	- Group Assign			
9366 🗸	FOYER / ENTRY- DOORS: 1-mirror Noset door frame bent	- Group Assign		That many replaced	doo
9367 🗸	LIVING/DINING ROOM- FLOORING-left wall by outlet - quarter round - chipped -see tape	- Group Assign	1		
9368	LIVING/DINING ROOM- WALLS- wall entering livingroom - right of kitchen entry paint touchup needed - see tape	- Group Assign			
9369	MAIN BATHROOM- DOORS- doorframe entering chipped top right - see/tape	- Group Assign			
9370	KITCHEN- COUNTERTOPS-granite needs more caulking under island -see tape	- Group Assign			

Date Completed:

Amacon Customer Care Signature:

feb 11/09/8

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back - Forms Menu

ID# 9363/9364/9365/9366/9367/9368/9369/9370 Eve Ph 1 Lot 2910