

AMACON

LIVE WELL

**Warranty Services
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 3001
Closing Date	3001 - 3515 Kariya
Date	0000
Contact Name(s)	10Feb09
Contact Telephone#	Kamal Damouni and Yasmine Damouni
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office


Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
9759	FOYER / ENTRY- WALLS-discoloration along bulkhead	→		CALL PAINTER.
9766	LIVING/DINING ROOM- WINDOWS-ALUMINUM scratched/marked around balcony door, see tape	✓		
9767	LIVING/DINING ROOM- WINDOWS: 1-ALUMINUM scratched left window, see tape	✓		
9769	LIVING/DINING ROOM- WALLS-left wall chips in paint, marked/patchy, see tape	→		CALL PAINTER.
9770	LIVING/DINING ROOM- WALLS: 1-marks and chips wall between window, see tape	✓		
9771	LIVING/DINING ROOM- WALLS: 2-chips and holes to right of window, see tape	✓		
9772	LIVING/DINING ROOM- WALLS: 3-right wall paint patchy/marked, see tape	→		CALL PAINTER.
9773	LIVING/DINING ROOM- WALLS: 4-right wall baseboard needs touch up to left of outlet, see tape	✓		
9774	LIVING/DINING ROOM- WALLS: 5-touch up wall to left of island, see tape	→		CALL PAINTER.
9775	LIVING/DINING ROOM- WALLS: 6-holes along baseboard below balcony sill, see tape	✓		
9776	MASTER BEDROOM- WALLS-seam showing left wall above outlet, see tape	✓		
9777	MASTER BEDROOM- WALLS: 1-seam showing left side bulkhead	✓		
9778	MASTER BEDROOM- WALLS: 2-hole in drywall, right wall by outlet, see tape	✓		
9779	MASTER BEDROOM- WALLS: 3-mark on drywall right wall below light switch, see tape	✓		
9780	MASTER BEDROOM- WALLS: 4-chips in baseboard to right of entry, see tape	✓		
9781	MASTER BEDROOM- WALLS: 5-marks on left wall and paint patchy, see tape	→		CALL PAINTER.
9782	MASTER BEDROOM- WALLS: 6-scratches in baseboard, left wall, see tape	✓		
9783	MASTER BEDROOM- WALLS: 7-hole in baseboard left end of window, see tape	✓		

9784	✓	MASTER BEDROOM- WALLS: 8-crack at left window sill, see tape	✓		
9785	✓	MASTER BEDROOM- WALLS: 9-drywall marked to right of vent, see taped	✓		
9786	✓	MASTER BEDROOM- CLOSET-marks on outside casing, see tape	✓		
9787	✓	MASTER BEDROOM- WINDOWS-ALUMINUM marked and scratched, see tape	✓		
9788	✓	MASTER BEDROOM- WINDOWS: 1-excessive silicone along aluminum frame, see tape	✓		
9789	✓	MAIN BATHROOM- TUB-silicone around showerhead, tap, faucet, see tape	✓		
9796	✓	KITCHEN- APPLIANCE-no power at stove	✓		
9797	✓	KITCHEN- CEILING-hole by light fixture facing windows	✓		

Date Completed:

FEBRUARY 10, 2008

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -
Forms
Menu

ID#

9759/9766/9767/9769/9770/9771/9772/9773/9774/9775/9776/9777/9778/9779/9780/9781/9782/9783/9784/9785/9786/9787/9788/9789/9796/9797
Eve Ph 1 Lot 3001