

AMACON

LIVE WELL

**Warranty Services
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827


Location	Eve - Tower: 1 - Unit: 3007 3007 - 3515 Kariya
Closing Date	0000
Date	10Feb09
Contact Name(s)	Hamid Shariati
Contact Telephone#	
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
10100	FOYER / ENTRY- DOORS-marks on frame, left side and along top, see tape	✓		
10101	FOYER / ENTRY- CLOSET-access panel not flush	✓		
10104	LIVING/DINING ROOM- ELECTRICAL/LIGHTING-outlet cover to left of main bathroom not flush, see tape	✓		
10105	LIVING/DINING ROOM- WINDOWS-ALUMINUM scratched/ marked, see tape	✓		
10106	LIVING/DINING ROOM- WINDOWS: 1-excess paint on ALUMINUM frame, see tape	✓		
10107	LIVING/DINING ROOM- WINDOWS: 2-ALUMINUM THRESHOLD not flush, see tape	✓		
10108	LIVING/DINING ROOM- WALLS-stipple on wall to right of window, see tape	✓		
10109	GUEST BEDROOM 1- WALLS-baseboard dented to left of closet, see tape	✓		
10110	GUEST BEDROOM 1- WINDOWS-marks and scratches around window frame, see tape	✓		
10111	MASTER BEDROOM- WALLS-chip in paint to left of window, see tape	✓		
10112	MASTER BEDROOM- WALLS: 1-mark to right of telephone jack, see tape	✓		
10113	MASTER BEDROOM- WALLS: 2-baseboard scratched, right wall, see tape	✓		
10114	MASTER BEDROOM- WALLS: 3-DRYWALL DENTED wall between windows, see tape	✓		
10115	MASTER BEDROOM- WALLS: 4-bulkhead by window cracked	✓		
10116	MASTER BEDROOM- WALLS: 5-mark at bulkhead in front of entrance	✓		
10117	MASTER BEDROOM- CLOSET-door doesn't slide properly, see tape	✓		
10118	MASTER BEDROOM- WINDOWS-ALUMINUM marked/ scratched, see tape	✓		
10119	MAIN BATHROOM- TUB-silicone around showerhead, tap, faucet, see tape	✓		
10120	MAIN BATHROOM- TOILET-toilet paper holder missing	✓		Done.
10121	ENSUITE BATHROOM- TUB-silicone around showerhead, tap, faucet, see tape	✓		
10122	ENSUITE BATHROOM- VANITY CABINETS-access panel cover not flush, see tape	✓		
10130	KITCHEN- WINDOWS-ALUMINUM scratched top windows, left wall	✓		
10131	KITCHEN- WINDOWS: 1-window sill cracked, left wall, see tape	✓		
10132	KITCHEN- WALLS-J-mold left side of balcony door has cracks, see tape	✓		

Date Completed:

FEBRUARY 11, 09

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to