



## Warranty Services Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

<b>Location</b>	<u>Eve - Tower: 1 - Unit: 3101</u> <u>3101 - 3515 Kariya</u>
<b>Closing Date</b>	0000
<b>Date</b>	11Feb09
<b>Contact Name(s)</b>	<u>Steven Wyzlic and Hubert Wyzlic</u>
<b>Contact Telephone#</b>	
<b>Company:</b>	<u>Amacon Service</u>
<b>Attention:</b>	<u>Carlos Bravo</u>
<b>Telephone:</b>	
<b>Fax:</b>	<u>(905) 848-2827</u>
<b>From:</b>	<u>Warranty Services Department - Head Office</u>

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
10226 ✓	FOYER / ENTRY- DOORS- marks/scratches on frame, see tape		✓	
10227 ✓	LIVING/DINING ROOM- WINDOWS-ALUMINUM frame at balcony door marked/scratched, see tape		✓	
10229 ✓	MAIN BATHROOM- WALLS-mark on left wall by outlet, see tape		✓	
10230 ✓	MAIN BATHROOM- WALLS: 1- marks/chip on right wall above countertop, see tape		✓	
10231 ✓	MAIN BATHROOM- DOORS-marks on inside casing near striker plate, see tape		✓	
10232 ✓	MAIN BATHROOM- TUB-silicone around showerhead , tap and faucet, see tape		✓	
10233 ✓	MAIN BATHROOM- TOILET-toilet paper holder missing		✓	
10237 ✓	KITCHEN- COUNTERTOPS-remove excess glue, see tape		✓	

Date Completed:

Feb 11/09 *KF*

Amacon Customer Care Signature:

*[Handwritten Signature]*