

**AMACON**

LIVE WELL

**Warranty Services****Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827


<b>Location</b>	<u>Eve - Tower: 1 - Unit: 3103</u> <u>3103 - 3515 Kariya</u>
<b>Closing Date</b>	<u>0000</u>
<b>Date</b>	<u>13Feb09</u>
<b>Contact Name(s)</b>	<u>Muhammad Nadeem</u>
<b>Contact Telephone#</b>	
<b>Company:</b>	<u>Amacon Service</u>
<b>Attention:</b>	<u>Carlos Bravo</u>
<b>Telephone:</b>	
<b>Fax:</b>	<u>(905) 848-2827</u>
<b>From:</b>	<u>Warranty Services Department - Head Office</u>

**Please complete the following items:**

Deficiency Number	Issue		Appointment Date/Time	Notes
11842	FOYER / ENTRY- WALLS-rightside on entering black mark above security rough in -see tape	✓		
11843	FOYER / ENTRY- WALLS: 1-black marks rightside of doorframe -see tape	✓		
11844	FOYER / ENTRY- DOORS-scratched doorframe by lock -see tape	✓		
11851	LIVING/DINING ROOM- WINDOWS: 1-balcony alUMINUM frame scratched leftside two areas - see tape c	✓		
11852	LIVING/DINING ROOM- CEILING-cracked above balcony window	✓		
11853	LIVING/DINING ROOM- CEILING: 1-hole surrounding heat sensor - see tape	✓		
11854	LIVING/DINING ROOM- WALLS-right wall by fancoil - pencil marks - see tape	✓		
11855	LIVING/DINING ROOM- WALLS: 1-right wall above outlet pencil marks - see tape	✓		
11856	LIVING/DINING ROOM- WALLS: 2-small wall between laundry closet and bathroom black marks above outlet -see tape	✓		
11857	MASTER BEDROOM- WALLS-hole in right wall by outlet - see tape	✓		
11858	MASTER BEDROOM- WALLS: 1-baseboard rightside by mirror closet doors - chipped - see tape	✓		
11859	MASTER BEDROOM- WALLS: 2-baseboard left corner cracked - see tape	✓		
11860	MASTER BEDROOM- WALLS: 2-baseboard left corner cracked - see tape	✓		
11861	MASTER BEDROOM- WALLS: 2-baseboard left corner cracked - see tape	✓		
11862	MASTER BEDROOM- CEILING-ceiling cracked by window	✓		
11863	MASTER BEDROOM- WINDOWS-window sill screws showing thru caulking - see tape	✓		
11864	DEN- CEILING-hole by light rough in	✓		
11865	MAIN BATHROOM- TUB-temperature control, faucet and showerhead - see tape	✓		

11866	MAIN BATHROOM- ELECTRICAL/LIGHTING-access panel open needs to be sealed - see tape	✓		
11869	KITCHEN- APPLIANCE-stove needs to be plugged in - see tape	✓		
11870	LAUNDRY CLOSET- NOTE-washer scratched bottom left corner	X		

Date Completed: FEB 14 2009

Amacon Customer Care Signature: 

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

**Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

Back -  
Forms  
Menu

ID#

11842/11843/11844/11851/11852/11853/11854/11855/11856/11857/11858/11859/11860/11861/11862/11863/11864/11865/11866/11869/11870  
 Eve Ph 1 Lot 3103