

AMACON

LIVE WELL

**Warranty Services
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 3205
Closing Date	3205 - 3515 Kariya
Date	0000
Contact Name(s)	12Feb09
Contact Telephone#	Liqun Fu
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:

Deficiency Number	Issue	Appointment Date/Time	Notes
11527	FOYER / ENTRY- WALLS-chips cornerto left of closet, see tape		
11528	FOYER / ENTRY- DOORS-door frame scratched, see tape		
11530	LIVING/DINING ROOM- ELECTRICAL/LIGHTING-fancoil unit dented, see tape		
11533	LIVING/DINING ROOM- WINDOWS: 1-ALUMINUM scratched, see tape		
11534	LIVING/DINING ROOM- WALLS-DRYWALL scratched to right of laundry closet, see tape		
11535	LIVING/DINING ROOM- WALLS: 1-right wall scratched by fancoil unit, see tape		
11536	LIVING/DINING ROOM- WALLS: 2-marks on wall to right of kitchen entrance, see tape		
11537	GUEST BEDROOM 1- WALLS-marks on right wall, see tape		
11538	GUEST BEDROOM 1- WALLS: 1-mark on left wall, see tape		
11539	MASTER BEDROOM- WALLS-DRYWALL DENTED to left of fancoil unit, see tape		
11540	MASTER BEDROOM- WALLS: 1-DRYWALL DENTED below window, see tape		
11541	MASTER BEDROOM- WALLS: 2-DRYWALL DENTED left wall by closet, see tape		
11542	MASTER BEDROOM- WALLS: 3-DRYWALL DENTED below braker panel at entrance, see tape		
11543	MASTER BEDROOM- WINDOWS-mark top right corner of window		
11544	DEN- WALLS-marks on right wall, see tape		
11545	DEN- WALLS: 1-mark on left wall, see tape		
11546	DEN- WALLS: 2-mark on back wall to left of cable outlet, see tape		
11549	DEN- ELECTRICAL/LIGHTING-cable outlet not straight, see tape		
11550	MAIN BATHROOM- TUB-silicone around showerhead, tap, faucet, see tape		
11551	ENSUITE BATHROOM- WALLS-2nd tile above soap dish marked, see tapw		
11552	ENSUITE BATHROOM- TUB-silicone around showerhead, tap, faucet, see tape		
11553	KITCHEN- FLOORING-regrout 3rd tile to right of fridge, see tape		
11559	KITCHEN- WINDOWS-ALUMINUM marked eat-in kitchen window, see tape		
11560	KITCHEN- WALLS-J-mold marked left side, window above sink, see tape		
11561	KITCHEN- WALLS: 1-DRYWALL DENTED to left of window, see tape		
11562	KITCHEN- WALLS: 2-drywall cracked to right of air vent above fridge, see tape		
11563	KITCHEN- WALLS: 3-holes in drywall of microwave bulkhead, see tape		
11564	LAUNDRY CLOSET- NOTE-marks on tiles un front of washer, see tape		
11566	LAUNDRY CLOSET- DOORS-chip inside door top corner, see tape		
11567	LAUNDRY CLOSET- WALLS-water shut off not attached to wall, see tape		

Date Completed:

Feb 13/09 18

Amacon Customer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827. Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -
Forms
Menu

ID#

11527/11528/11530/11533/11534/11535/11536/11537/11538/11539/11540/11541/11542/11543/11544/11545/11546/11549/11550/11551/11552/11553/11559/11560/11561/11562/11563/11564/11566/
Eve Ph 1 Lot 3205