AMACON

Warranty Services Work Order

LIVE WELL Phone: (905) 848-2069 Fax:(905) 848-2827

Location **Eve - Tower: 1 - Unit: 3502**

0000

31Mar09

Curtis Fagan

3502 - 3515 Kariya

Closing Date

Date

Contact Name(s)

Contact Telephone#

Company: Attention:

Amacon Service Carlos Bravo

Telephone:

Fax:

(905) 848-2827

Warranty Services Department - Head Office From:

Deficiency Number	Issue	 Appointment Date/Time	Notes
12294	FOYER / ENTRY- WALLS-wall above mirror closet doors left edge paint chipped - see tape		
12295	FOYER / ENTRY- WALLS: 1-bottom right corner above baseboard paint touchup needed - see tape		
12296	FOYER / ENTRY- WALLS: 2-bottom right corner by mirror excess paint - see tape		
12297	FOYER / ENTRY- DOORS-doorframe scratched top left - see tape		
12298	FOYER / ENTRY- DOORS: 1- doorframe scratched bottom right corner- see tape		
12299	FOYER / ENTRY- DOORS: 2-paint on mirror closet door valance - see tape		_
12306	LIVING/DINING ROOM- WALLS- wall is matked under balcony stairs - 3 spots - see tape		
12307	LIVING/DINING ROOM- WALLS: 1- nail pop in baseboard below outlet - right wall - see tape		
12308	LIVING/DINING ROOM- WALLS: 2- wall leading to bathroom - rightside scratched - black marks - see tape		

12309	MASTER BEDROOM- WALLS-right wall on entering black marks - see tape		
12310	MASTER BEDROOM- WALLS: 1- black marks centre wall by balcony door see tape		
12311	MASTER BEDROOM- ELECTRICAL/LIGHTING-fire alarm signal upside down - see tape		
12312	MASTER BEDROOM- ELECTRICAL/LIGHTING: 1- electrical panel missing a screw - see tape		
12315	KITCHEN- CABINETS: 2-more silicone needed under kitchen island and granite - see tape		
12318	KITCHEN- APPLIANCE-fridge scratched - see tape		

Date Completed:	ı	
malen 23	03	
		(

Amacon Customer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back - Forms Menu

ID#

12294/12295/12296/12297/12298/12299/12306/12307/12308/12309/12310/12311/12312/12315/12318 Eve Ph 1 Lot 3502