

**AMACON**

LIVE WELL

**Warranty Services  
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

<b>Location</b>	<u>Eve - Tower: 1 - Unit: 3703</u>
<b>Closing Date</b>	<u>3703 - 3515 Kariya</u>
<b>Date</b>	<u>0000</u>
<b>Contact Name(s)</b>	<u>23Feb09</u>
<b>Contact Telephone#</b>	<u>Amin Alhamad</u>
<b>Company:</b>	<u>Amacon Service</u>
<b>Attention:</b>	<u>Carlos Bravo</u>
<b>Telephone:</b>	
<b>Fax:</b>	<u>(905) 848-2827</u>
<b>From:</b>	<u>Warranty Services Department - Head Office</u>

**Please complete the following items:**

Deficiency Number	Issue	Appointment Date/Time	Notes
13083	FOYER / ENTRY- WALLS-paint chipped to right of closet, see tape	- Group Assign	
13084	FOYER / ENTRY- WALLS: 1-mark on back closet wall, see tape	- Group Assign	
13085	FOYER / ENTRY- WALLS: 2-coners chipped right wall, see tape	- Group Assign	
13086	FOYER / ENTRY- DOORS: 1-scratches on frame, see tape	- Group Assign	
13087	LIVING/DINING ROOM- WINDOWS-marks and scratches around window, see tape	- Group Assign	
13088	LIVING/DINING ROOM- WINDOWS: 1-excessive silicone window panel to right of windows, see tape	- Group Assign	
13089	LIVING/DINING ROOM- WINDOWS: 2-ALUMINUM THRESHOLD loose, see tape	- Group Assign	
13090	GUEST BEDROOM 1- WALLS-mark on wall opposite windows, see tape	- Group Assign	
13091	GUEST BEDROOM 1- DOORS-door stop missing	- Group Assign	
13092	GUEST BEDROOM 1- DOORS: 1-chip on front of door right side, see tape	- Group Assign	
13093	GUEST BEDROOM 1- DOORS: 2-casing chipped right side, see tape	- Group Assign	
13094	GUEST BEDROOM 1- FLOORING-gap at baseboard to right of window, see tape	- Group Assign	
13095	GUEST BEDROOM 1- ELECTRICAL/LIGHTING-light switch cover not flush, see tape	- Group Assign	
13096	GUEST BEDROOM 1- WINDOWS-glue around windows, see tape	- Group Assign	
13097	GUEST BEDROOM 1- WINDOWS: 1-mark on inside of sliding window, see tape	- Group Assign	
13098	GUEST BEDROOM 2- WALLS-mark on right wall in front of window, see tape	- Group Assign	
13099	GUEST BEDROOM 2- DOORS-door stop missing	- Group Assign	
13100	GUEST BEDROOM 2- DOORS: 1-mark on bottom front and backside of door, see tape	- Group Assign	
13101	GUEST BEDROOM 2- FLOORING-CLEAN CARPET	- Group Assign	
13102	GUEST BEDROOM 2- CLOSET-doors missing	- Group Assign	
13103	GUEST BEDROOM 2- WINDOWS-excess glue around windows, see tape	- Group Assign	
13104	GUEST BEDROOM 2- WINDOWS: 1-window stop not flush east facing window, right side, see tape	- Group Assign	
13105	MASTER BEDROOM- WALLS-DRYWALL DENTED below thermostat, see tape	- Group Assign	
13106	MASTER BEDROOM- WALLS: 1-gap at bottom of j-mold right window, see tape	- Group Assign	
13107	MASTER BEDROOM- CLOSET-chipped casing, walk-in closet, right side, see tape	- Group Assign	
13108	MASTER BEDROOM- ELECTRICAL/LIGHTING: 2-overspray paint on fire alarm silencer, see tape	- Group Assign	
13109	MASTER BEDROOM- WINDOWS-glue and marks around windows, see tape	- Group Assign	
13110	MASTER BEDROOM- WINDOWS: 1-BALCONY SILL marked, right side, see tape	- Group Assign	
13111	MASTER BEDROOM- WINDOWS: 2-BALCONY SILL chipped, see tape	- Group Assign	

13112	MASTER BEDROOM- WINDOWS: 3-marks and scratches around balcony door, see tape	- Group Assign	✓	
13113	DEN- WALLS-chipped corner right wall, see tape	- Group Assign	✓	
13114	MAIN BATHROOM- DOORS-outside casing chipped, see tape	- Group Assign	✓	
13115	MAIN BATHROOM- DOORS: 1-excessive gap top right corner, see tape	- Group Assign	✓	
13116	MAIN BATHROOM- DOORS: 2-wrong door hardware--no lock	- Group Assign	✓	
13117	MAIN BATHROOM- DOORS: 3-excessive gap top left corner inside, see tape	- Group Assign	✓	
13118	MAIN BATHROOM- DOORS: 4-door doesn't close properly	- Group Assign	✓	
13119	MAIN BATHROOM- DOORS: 5-door rubbing against casing on left side	- Group Assign	✓	
13120	MAIN BATHROOM- DOORS: 6-stain bottom of casing right side, see tape	- Group Assign	✓	
13121	MAIN BATHROOM- COUNTERTOPS-left corner of backsplash needs silicone and is not flush, see tape	- Group Assign	—	Mark
13122	MAIN BATHROOM- COUNTERTOPS: 1-right corner at backsplash not flush, see tape	- Group Assign	—	Mark
13123	ENSUITE BATHROOM- WALLS-DRYWALL DENTED in front of vanity, see tape	- Group Assign	✓	
13124	ENSUITE BATHROOM- WALLS: 1-holes along front of tub along tiles, see tape	- Group Assign	✓	
13125	ENSUITE BATHROOM- WALLS: 2-mark below towel rack, see tape	- Group Assign	✓	
13126	ENSUITE BATHROOM- DOORS-top front of door rough, see tape	- Group Assign	✓	
13127	ENSUITE BATHROOM- DOORS: 1-mark around front door handle, see tape	- Group Assign	✓	
13128	ENSUITE BATHROOM- DOORS: 2-door stop missing	- Group Assign	✓	
13129	ENSUITE BATHROOM- DOORS: 3-lock missing	- Group Assign	✓	
13130	ENSUITE BATHROOM- DOORS: 4-chip upper rear left side, see tape	- Group Assign	✓	
13131	ENSUITE BATHROOM- DOORS: 5-chips in casing, see tape	- Group Assign	✓	
13132	ENSUITE BATHROOM- TUB: 1-grout required top of accent tile, see tape	- Group Assign	✓	
13133	ENSUITE BATHROOM- COUNTERTOPS-backsplash not flush, see tape	- Group Assign	—	Mark
13134	KITCHEN- CABINETS: 6-excessive gap cabinet above dishWASHER, see tape	- Group Assign	—	Kitchen's
13135	KITCHEN- CABINETS: 7-excessive silicone on dishWASHER gable, see tape	- Group Assign	—	11 11
13136	KITCHEN- COUNTERTOPS-excessive gap underside of countertop at dishWASHER gable, see tape	- Group Assign	—	11 11
13137	KITCHEN- ELECTRICAL/LIGHTING-BULBS BURNED OUT	- Group Assign	✓	
13138	KITCHEN- WINDOWS-mark to left of balcony door, see tape	- Group Assign	✓	
13139	KITCHEN- WINDOWS: 1-ALUMINUM marked top panel to right of balcony door	- Group Assign	✓	
13140	KITCHEN- WINDOWS: 2-excessive silicone along left side of balcony door, see tape	- Group Assign	✓	
13141	KITCHEN- WALLS-marks on j-mold, see tape	- Group Assign	✓	
13142	LAUNDRY CLOSET- NOTE-please close secondary lint trap	- Group Assign	✓	
13143	LAUNDRY CLOSET- WALLS-marks on walls, see tape	- Group Assign	✓	
13144	FOYER / ENTRY- DOORS-varnish back of entry door		✓	
13149	LIVING/DINING ROOM- ELECTRICAL/LIGHTING: 1-thermostat showing code SF			must change
13155	DEN- FLOORING: 1-baseboard chipped, back wall, see tape		✓	

Date Completed:

Feb 24/09 18

Amacon Customer Care Signature:

M. Fritz

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827. Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.