,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			~~			- 1
A	M	A	C	0	N	and the same of

Warranty Services Work Order Phone: (905) 848-2069 Fax: (905) 848-2827

WELL LIVE

Location	Eve - Tower: 1 - Unit: 706
	<u>706 - 3515 Kariya</u>
Closing Date	0000
Date	08Jan09
Contact Name(s)	Nenad Samardzija and Sonja Samardzija
Contact Telephone#	· · · · · · · · · · · · · · · · · · ·
Company:	Amacon Service
Attention:	<u>Carlos</u> <u>Brav</u> o
Telephone:	
Fax:	(9 <u>05)</u> <u>848-2827</u>
From:	Warranty Services Department - Head Office

lease c	omplete the following items:			Notes
Deficiency Number	Issue	li li	Appointment Date/Time	11005
804	LIVING/DINING ROOM- FLOORING-baseboard chipped right wall ADJACENT TO laundry closet			
2811	LIVING/DINING ROOM- WINDOWS-draft coming from left of balcony sill			
2812 /	LIVING/DINING ROOM- WALLS- mark above fan coil unit left side		L	
2814	GUEST BEDROOM 1- DOORS: 1- excessive gap top left corner of interior			,
2815 /	GUEST BEDROOM 1- ELECTRICAL/LIGHTING-cover plate Loose by window.			
2816	MASTER BEDROOM- WALLS- DRYWALL rough left of closet 6 feet from floor		1/	
2817 /	MASTER BEDROOM- DOORS-gap top left casing exterior door frame		I	
2819	MASTER BEDROOM- CEILING- erack by bulkhead in front of window			
2820)	MASTER BEDROOM- CLOSET-gap interior frame top left corner			<u> </u>
2821 *	MASTER BEDROOM- CLOSET: 1- gap exterio frame top left and right			

<u> </u>	corpier		
	MASTER BEDROOM- ELECTRICAL/LIGHTING-straighten fire alarm silencer		
	MASTER BEDROOM- WINDOWS: 1-draft coming from lower right window		allan windows.
2831	ENSUITE BATHROOM- TUB- SILICONE SPOUT		
2842	LAUNDRY CLOSET- DOORS-interior frame scratched upper left side		

Date Cor	np	leted:	1 12	H Mark
JAN	ŧ	0	109	_K
		- 44	∉	

Amaçon Customer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back - Forms Menu

ID# 2804/2811/2812/2814/2815/2816/2817/2819/2820/2821/2822/2826/2831/2842 Eve Ph 1 Lot 706