

WORK ORDER

port Run Date:

7/7/2009

| | | | |
|---|--|--|--|
| Whirlpool Canada LP 1901 Minnesota Ct. Mississauga, Ont. L5N 3A7 1-800-807-6777 | | Dispatch Number: D391548243 Dispatch Status: Accepted Dispatch Date: July 06, 2009 Date Accepted: July 07, 2009 Scheduled Service Date: July 12, 2009 Scheduled Service Time: All Day | |
| GST #R849582879 QST #1207913550 | | | |

Model Number YWET3300SQ1

Serial Number MW5210095

Purchase Date 04/28/09

Recall/Rework Number

Payment Type

In Warranty

Payment Terms

Consumer Information

Name (Last, First) Grahame Amacon, Leah Maio

Address* 908-3515 Kariya Dr

908

City, Province, Postal Code Mississauga ON L5B0C1

Home Phone 4163699069

Alt. Phone

Directions/Cross Streets Next to Square One

Zone Id DEFAULT

Work Phone 9052749520

Special Instructions Grahame W from Builder will facilitate repair

Problem Description PROPERTY DAMAGE leaking water pls fax report to CR 9058216698

Service Instruction

Call Received Date

Time Started

Time on Job (hours)

Warranty: Labor _____ Months Parts _____ Months

Service Explanation

Estimate [] valid for _____ Days Date:

Service Date

Time Completed

Hourly Rate _____ for the first _____ minutes
for each additional _____ minutes

| Quantity | Part # | Invoice # | Unit Part Cost | Extension | Item | Amount |
|----------|--------------|-----------|----------------|---------------------|-----------------|--------|
| | | | | | Sub Total Parts | |
| | Description: | | | New [] Rebuilt [] | Handling | |
| | | | | | Total Parts | |
| | Description: | | | New [] Rebuilt [] | Labor | |
| | | | | | Total Labor | |
| | Description: | | | New [] Rebuilt [] | Freight | |
| | | | | | Travel | |
| | Description: | | | New [] Rebuilt [] | PST/QST | |
| | | | | | GST/HST | |
| | Description: | | | New [] Rebuilt [] | Total Amount | |

Customer Signature

Credit Card Number

Expiration Date