

Warranty Services Service Call

*Eve - 707
upload to
PASS*

Company: Barwood Flooring
Attention:
Telephone:
Fax: (416) 431-2393
From: Ed Valencia
Date: 13Dec10
Location: Site:Eve Phase: 1 Lot: 707
707 - 3515 Kariya
Contact Name(s): Alfonso Camaioni
Contact Telephone#

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Please complete the following items:

Issue	Appointment Date	Appointment Time	Completion Date
Hardwood floor have lift up on different areas / Also visible gaps			

Date Completed: DEC 13, 2010

Purchaser Signature: *Alfonso Camaioni*

Faxed:						
--------	--	--	--	--	--	--

[Back](#)

ID# 24587 Eve Ph 1 Lot 707

Deficiency History

Lot:2902 Elle - Phase: Elle

6

Same Note 5

<u>Work Order Date</u>	<u>Type</u>	<u>Deficiency Description</u>	<u>Trade</u>	<u>Close Date or Status</u>	<u>Days Open</u>
03Sept10	PDI	FOYER / ENTRY- DOORS-top right corner of doorframe touch u	Amacon Service	16Sept10	13
03Sept10	PDI	LIVING/DINING ROOM- FLOORING-multiple markings on flooring marked	Barwood Flooring	15Dec10	103
03Sept10	PDI	LIVING/DINING ROOM- WINDOWS-window frame beside master bedroom touchup where marked	Amacon Service	16Sept10	13
03Sept10	PDI	LIVING/DINING ROOM- WALLS-doorframe around master bedroom touchup all around	Amacon Service	16Sept10	13
03Sept10	PDI	GUEST BEDROOM 1- WALLS-bottom right of cold air return vent touchup on wall	Amacon Service	16Sept10	13
03Sept10	PDI	MASTER BEDROOM- WINDOWS-middle window frame right side touchup where marked	Amacon Service	16Sept10	13
03Sept10	PDI	MAIN BATHROOM- VANITY CABINETS-grout missing back of cabinet inside	Amacon Service	16Sept10	13
03Sept10	PDI	MAIN BATHROOM- ELECTRICAL/LIGHTING-light bulb burnt out	Amacon Service	16Sept10	13
03Sept10	PDI	KITCHEN- CABINETS-outside island facing living room holes where marked	Cartier Kitchens	12Oct10	39

Total Reported Deficiencies: 9 / Average Days Open: 25

Customer Info

Requested
Documentation removed (01/10/2011)
Homeowner called to say that flooring items not
completed w/ several other items.
- Barwood - 01/11/2010
UPCOMING TO PASS