

Mark Fritz

From: Grahme Walsh
To: Mark Fritz
Cc: Manuela Castiglione
Subject: Service Request: 607
Attachments:

Sent: Tue 1/5/2010 12:38 PM

Service Request: 607

Contact: Hoang

Contact Number: 416-399-9397

Service Request:

EW 607

2nd bedroom blowing cold air causing under door?

investigate on Jan-07-10

2nd bedroom no heat

Kitchen cabinets is defective

Lisi thermostat

Master bedroom – one mirror door loose

Balcony cement tile broken outside master bedroom

She says that this has been submitted 3-4 times in the last year – nobody has gotten back

Says has spoken to Rau!? And he saw and agreed with the issues

Permission to enter: Authorized

GRAHME WALSH
CONTRACTS MANAGER, CONSTRUCTION