

**Mark Fritz**

**From:** R LEUNG [rositaleung@rogers.com]  
**To:** Mark Fritz  
**Cc:**  
**Subject:** Re: Suite 1903  
**Attachments:**

**Sent:** Tue 1/5/2010 11:32 PM

Hi Mark,  
 Thx for dropping by today.

As discussed, please come by to adjust the gasket between the faucet and the bathroom sink any time after 9am in the next few days. If you cannot make it this week, please let me know another day.

Thx again.  
 Rosita

--- On Tue, 1/5/10, Mark Fritz <mfritz@amacon.com> wrote:

From: Mark Fritz <mfritz@amacon.com>  
 Subject: Re: Suite 1903  
 To: rositaleung@rogers.com  
 Date: Tuesday, January 5, 2010, 3:06 PM

*Completed  
 Jan - 07 10*

-----Original Message-----

From: R LEUNG <rositaleung@rogers.com>  
 To: Mark Fritz  
 Sent: Tue Jan 05 07:01:52 2010  
 Subject: Re: Suite 1903

Yes, see you later then.

--- On Tue, 1/5/10, Mark Fritz <mfritz@amacon.com> wrote:

From: Mark Fritz <mfritz@amacon.com>  
 Subject: Re: Suite 1903  
 To: rositaleung@rogers.com  
 Date: Tuesday, January 5, 2010, 3:04 PM

Sure no problem, how about 1:30

-----Original Message-----

From: R LEUNG <rositaleung@rogers.com>  
 To: Mark Fritz  
 Sent: Tue Jan 05 06:58:30 2010  
 Subject: RE: Suite 1903

Hi Mark,  
 I am home today. Can you drop by any time this afternoon (after 1pm) so I can show you the problems.

Thx.  
Rosita

--- On Mon, 1/4/10, Mark Fritz <mfritz@amacon.com> wrote:

From: Mark Fritz <mfritz@amacon.com>  
Subject: RE: Suite 1903  
To: "R LEUNG" <rositaleung@rogers.com>  
Date: Monday, January 4, 2010, 8:28 PM

Hi Rosita,

Happy New Year to you as well !

I am free anytime this week, Please let me know when is best for you.

Thanks

Mark Fritz  
Amacon Construction

Customer Service Representative

---

From: R LEUNG [<mailto:rositaleung@rogers.com>]  
Sent: Mon 1/4/2010 2:27 PM  
To: Mark Fritz  
Subject: Suite 1903

Hi Mark,

Happy New Year !

The bathroom sink faucet is leaking water to the cabinate again. I don't want any more silicone applied because it collects mold at the back. The problem is that the plastic gasket between the faucet and ceramic was not installed properly and was shifted, exposing the back.

Also the electric outlet on the left side close to the window in the living room doesn't work.

Can you let me know when you can look at them.

Thank you.  
Rosita Leung