

1907
DONE ✓
MANAGER
Ed Valencia

From: Grahme Walsh
To: Ed Valencia
Cc:
Subject: Service REquest
Attachments:


Sent: Tue 3/9/2010 12:21 PM

Ed:

1907 – cabinet to be re-attached – one year warranty has expired – see what it entails

GRAHME WALSH
CONTRACTS MANAGER, CONSTRUCTION

*Unit #1907.
Completed.*



L I V E W E L L

2 Harbour Street
Toronto, Ontario, M5J 2Z3
Tel. 416.369.9069
Fax. 416.369.9068
Email. gwalsh@amacon.com
Web. www.amacon.com

This e-mail is intended only for the named recipient(s) and may contain information that is privileged, confidential and/or exempt from disclosure under applicable law. No waiver of privilege, confidence or otherwise is intended by virtue of communication via the internet. Any unauthorized use, dissemination or copying is strictly prohibited. If you have received this e-mail in error, or are not named as a recipient, please immediately notify the sender and destroy all copies of this e-mail. Please be aware that internet communications are subject to the risk of data corruption and other transmission errors. For information of extraordinary sensitivity, we recommend that our clients use encryption software when they communicate with us by e-mail.

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5H 2B1

TEL: 416-363-5063 FAX: 416-363-5065
905-232-4636

905-232-4637 (Fax to Amaccon)
CUSTOMER CARE

ATTENTION CUSTOMER CARE: 2515 KARIYA DR.

TEL: 905-848-2023 FAX: 905-848-2827

NAME: Danny Vain

SUITE: 1907

DEVELOPMENT NAME: _____

ADDRESS: 3515 Kariya Dr.

REST: _____

BUS. TEL: _____

CELL: (647) 892-3163

FAX: _____

EMAIL: _____

DATE OF REQUEST: March 9, 2010

SERVICE REQUEST:

1. Kitchen lower right corner cabinet door broken
2. beside stove need to be re-attached ✓
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____
9. _____
10. _____

1 Authorize suite entry
[Signature]