

Grahme Walsh

Eve 3605

From: Chantal Andrade
Sent: Wednesday, March 02, 2011 1:59 PM
To: Grahme Walsh
Subject: 3605 Eve

Updated to Pass

Work Order Date	Type	Deficiency Description	Trade	Close Date or Status	Days Open
06May09	Quality Control	Kitchen- cracked tile on backsplash and grout around counter	Megacity Tile	06May09	0
21Feb09	PDI	FOYER / ENTRY- WALLS-mark on left wall, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	FOYER / ENTRY- DOORS-touch up frame	Amacon Service	25Feb09	4
21Feb09	PDI	FOYER / ENTRY- FLOORING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	FOYER / ENTRY- CEILING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	FOYER / ENTRY- CLOSET-access panel not flush	Amacon Service	25Feb09	4
21Feb09	PDI	FOYER / ENTRY- ELECTRICAL/LIGHTING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	LIVING/DINING ROOM- FLOORING-excessive gap under quarter round, to left of cable outlet, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	LIVING/DINING ROOM- ELECTRICAL/LIGHTING-filter missing in fanCOIL unit	Lisi Mechanical	17Jul09	146
21Feb09	PDI	LIVING/DINING ROOM- WINDOWS-ALUMINUM THRESHOLD not flush, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	LIVING/DINING ROOM- CEILING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	LIVING/DINING ROOM- WALLS-mark by tri-light switch, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	GUEST BEDROOM 1- WALLS-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	GUEST BEDROOM 1- DOORS-scratches/chips inside casing, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	GUEST BEDROOM 1- DOORS: 1-chips outside casing seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	GUEST BEDROOM 1- FLOORING-O.K. CLEAN CARPET	T & A Cleaning	04Nov09	256
21Feb09	PDI	GUEST BEDROOM 1- CEILING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	GUEST BEDROOM 1- CLOSET-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	GUEST BEDROOM 1- ELECTRICAL/LIGHTING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	GUEST BEDROOM 1- WINDOWS-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	GUEST BEDROOM 2- WALLS-mark on left wall below braker panel, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	GUEST BEDROOM 2- WALLS: 1-patch on left wall above telephone jack, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	GUEST BEDROOM 2- DOORS-chip on front bottom of door, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	GUEST BEDROOM 2- DOORS: 1-chips on front door, right side, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	GUEST BEDROOM 2- DOORS: 2-casing chipped, seeTAPE	Amacon Service	25Feb09	4

21Feb09	PDI	GUEST BEDROOM 2- FLOORING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	GUEST BEDROOM 2- CEILING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	GUEST BEDROOM 2- CLOSET-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	GUEST BEDROOM 2- ELECTRICAL/LIGHTING-no cable outlet	DECC Electric	15Mar09	22
21Feb09	PDI	GUEST BEDROOM 2- WINDOWS-centre stop missing left window, seeTAPE	Allan Windows	25Jun09	124
21Feb09	PDI	MASTER BEDROOM- WALLS-DRYWALL DENTED to left of walk-in closet, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	MASTER BEDROOM- DOORS-chip inside casing, left side, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	MASTER BEDROOM- FLOORING-pull in carpet at entrance	Quality Rugs	30Mar09	37
21Feb09	PDI	MASTER BEDROOM- FLOORING: 1-pull in carpet by left wall, seeTAPE	Quality Rugs	30Mar09	37
21Feb09	PDI	MASTER BEDROOM- CEILING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	MASTER BEDROOM- CLOSET-chips on walk-in closet door, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	MASTER BEDROOM- CLOSET: 1-top of baseBOARD rough, right side, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	MASTER BEDROOM- ELECTRICAL/LIGHTING-filter missing in fanCOIL unit	Amacon Service	25Feb09	4
21Feb09	PDI	MASTER BEDROOM- WINDOWS-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	DEN- WALLS-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	DEN- FLOORING-excessive gap under quarter round, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	DEN- FLOORING-excessive gap under quarter round, seeTAPE	Barwood Flooring	25Feb09	4
21Feb09	PDI	DEN- CEILING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	DEN- ELECTRICAL/LIGHTING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	MAIN BATHROOM- WALLS-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	MAIN BATHROOM- DOORS-side of door chipped at bottom, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	MAIN BATHROOM- DOORS: 1-chip outside casing, left side, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	MAIN BATHROOM- TUB-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	MAIN BATHROOM- TOILET-toilet seat lid scratched, seeTAPE	Lisi Mechanical	17Jul09	146
21Feb09	PDI	MAIN BATHROOM- CEILING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	MAIN BATHROOM- SINK-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	MAIN BATHROOM- COUNTERTOPS-excess silicone above toilet, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	MAIN BATHROOM- VANITY CABINETS-shelf chipped, seeTAPE	Cartier Kitchens	30Mar09	37
21Feb09	PDI	MAIN BATHROOM- VANITY CABINETS: 1-front of vanity door scratched, seeTAPE	Cartier Kitchens	30Mar09	37
21Feb09	PDI	MAIN BATHROOM- FLOORING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	MAIN BATHROOM- ELECTRICAL/LIGHTING-O.K.	Amacon - PDI - OK	23Feb09	2

21Feb09	PDI	ENSUITE BATHROOM- WALLS-mark inside vanity, seeTAPE	Cartier Kitchens	25Feb09	4
21Feb09	PDI	ENSUITE BATHROOM- DOORS-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	ENSUITE BATHROOM- TUB-mark on front panel, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	ENSUITE BATHROOM- TUB: 1-accent tiles chipped, seeTAPE	Megacity Tile	06May09	74
21Feb09	PDI	ENSUITE BATHROOM- TOILET-toilet seat lid scratched, seeTAPE	Lisi Mechanical	17Jul09	146
21Feb09	PDI	ENSUITE BATHROOM- SINK-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	ENSUITE BATHROOM- COUNTERTOPS-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	ENSUITE BATHROOM- CEILING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	ENSUITE BATHROOM- VANITY CABINETS-shelf chipped , seeTAPE	Cartier Kitchens	30Mar09	37
21Feb09	PDI	ENSUITE BATHROOM- VANITY CABINETS: 1-side of vanity cabinet chipped by floor, seeTAPE	Cartier Kitchens	30Mar09	37
21Feb09	PDI	ENSUITE BATHROOM- FLOORING-gap at rear of tub, seeTAPE	Amacon Service	25Feb09	4
21Feb09	PDI	ENSUITE BATHROOM- ELECTRICAL/LIGHTING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	KITCHEN- FLOORING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	KITCHEN- CABINETS-dishWASHER gable scratched and excessive silicone under countertop, seeTAPE	Cartier Kitchens	30Mar09	37
21Feb09	PDI	KITCHEN- CABINETS: 1-excessive gap in lazy susan cabinet, seeTAPE	Cartier Kitchens	30Mar09	37
21Feb09	PDI	KITCHEN- CABINETS: 2-handle loose cabinet above sink, seeTAPE	Cartier Kitchens	23Mar09	30
21Feb09	PDI	KITCHEN- COUNTERTOPS-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	KITCHEN- SINK-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	KITCHEN- APPLIANCE-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	KITCHEN- ELECTRICAL/LIGHTING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	KITCHEN- CEILING-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	KITCHEN- WINDOWS-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	KITCHEN- BACKSPLASH-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	KITCHEN- WALLS-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	LAUNDRY CLOSET- DOORS-O.K.	Amacon - PDI - OK	23Feb09	2
21Feb09	PDI	LAUNDRY CLOSET- WALLS-O.K.	Amacon - PDI - OK	23Feb09	2

CHANTAL ANDRADE
OFFICE ADMINISTRATOR