

### Deficiency History Lot:3703 Eve - Phase: 1

*UR on vto pass*  
*Eve - 3703*

| <u>Work Order Date</u> | <u>Type</u> | <u>Deficiency Description</u>                             | <u>Trade</u>     | <u>Close Date or Status</u> | <u>Days Open</u> |
|------------------------|-------------|-----------------------------------------------------------|------------------|-----------------------------|------------------|
| <u>01Mar10</u>         | 1 Year      | Living Room- Different floor weight                       | Barwood Flooring | 13Apr10                     | 43               |
| <u>01Mar10</u>         | 1 Year      | Living Room- Different floor weight                       | Barwood Flooring | 13Apr10                     | 43               |
| <u>01Mar10</u>         | 1 Year      | Bedroom- A/C not working well                             | Lisi Mechanical  | 12Apr10                     | 42               |
| <u>01Mar10</u>         | 1 Year      | Foyer- Main door needs to change                          | Amacon Service   | 15Apr10                     | 45               |
| <u>01Mar10</u>         | 1 Year      | Kitchen- Cabinets not stable                              | Kabinetz         | 04May10                     | 64               |
| <u>01Mar10</u>         | 1 Year      | Other- Balcony ceiling not complete finish                | N/A              | 15Apr10                     | 45               |
| <u>01Mar10</u>         | 1 Year      | Kitchen- Water pressure is very low                       | N/A              | 15Apr10                     | 45               |
| <u>01Mar10</u>         | 1 Year      | Throughout- All windows leak air                          | Allan Windows    | 20May10                     | 80               |
| <u>13Jul09</u>         | 30-Day      | Living Room- Different floor heights in all the rooms     | Barwood Flooring | 13Jul09                     | 0                |
| <u>13Jul09</u>         | 30-Day      | Bedroom- No cabinet doors                                 | Cartier Kitchens | 13Jul09                     | 0                |
| <u>13Jul09</u>         | 30-Day      | Bedroom- Conditioner not working well                     | Lisi Mechanical  | 13Jul09                     | 0                |
| <u>13Jul09</u>         | 30-Day      | Main Bathroom- Doors unstable and locks not working       | Amacon Service   | 04Nov09                     | 114              |
| <u>13Jul09</u>         | 30-Day      | Kitchen- Countertop not stable to the lower cabinet       | Megacity Granite | 04Nov09                     | 114              |
| <u>13Jul09</u>         | 30-Day      | Kitchen- Sinks not stable                                 | Lisi Mechanical  | 13Jul09                     | 0                |
| <u>13Jul09</u>         | 30-Day      | Kitchen- Dishwasher tube is very long and might leak      | Amacon Service   | 13Jul09                     | 0                |
| <u>13Jul09</u>         | 30-Day      | Kitchen- Sink water is low                                | Lisi Mechanical  | 13Jul09                     | 0                |
| <u>13Jul09</u>         | 30-Day      | Kitchen- Cabinets unstable                                | Cartier Kitchens | 13Jul09                     | 0                |
| <u>13Jul09</u>         | 30-Day      | Shared Bathroom- Sink is not stable                       | Lisi Mechanical  | 13Jul09                     | 0                |
| <u>26May09</u>         | 30-Day      | Different floor heights in all the                        | Barwood Flooring | 11Jun09                     | 16               |
| <u>26May09</u>         | 30-Day      | Bedroom- No cabinet doors.                                | Cartier Kitchens | 11Jun09                     | 16               |
| <u>26May09</u>         | 30-Day      | Bedroom- Air conditioner not working well                 | Lisi Mechanical  | 11Jun09                     | 16               |
| <u>26May09</u>         | 30-Day      | Doors unstable and locks not working in Bathroom          | Amacon Service   | 11Jun09                     | 16               |
| <u>26May09</u>         | 30-Day      | Kitchen- Counter top is not stable to the lower cabinets. | Amacon Service   | 11Jun09                     | 16               |

|                |        |                                                                                              |                      |         |    |
|----------------|--------|----------------------------------------------------------------------------------------------|----------------------|---------|----|
| <u>26May09</u> | 30-Day | Kitchen- Sink is not stable                                                                  | Lisi<br>Mechanical   | 11Jun09 | 16 |
| <u>26May09</u> | 30-Day | Kitchen- Dishwasher tube is very long and may leak.                                          | Lisi<br>Mechanical   | 11Jun09 | 16 |
| <u>26May09</u> | 30-Day | Kitchen- Sink water pressue is low.                                                          | Lisi<br>Mechanical   | 11Jun09 | 16 |
| <u>26May09</u> | 30-Day | Kitchen- Cabinets are unstable.                                                              | Cartier<br>Kitchens  | 13Jul09 | 48 |
| <u>26May09</u> | 30-Day | Main Bathroom- Cabinets are unstable                                                         | Cartier<br>Kitchens  | 11Jun09 | 16 |
| <u>23Feb09</u> | PDI    | FOYER / ENTRY- WALLS-paint chipped to right of closet, see tape                              | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI    | FOYER / ENTRY- WALLS: 1-mark on back closet wall, see tape                                   | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI    | FOYER / ENTRY- WALLS: 2-coners chipped right wall, see tape                                  | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI    | FOYER / ENTRY- DOORS-varnish back of entry door                                              | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI    | FOYER / ENTRY- DOORS: 1-scratches on frame, see tape                                         | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI    | FOYER / ENTRY- FLOORING-O.K.                                                                 | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI    | FOYER / ENTRY- CEILING-O.K.                                                                  | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI    | FOYER / ENTRY- CLOSET-O.K.                                                                   | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI    | FOYER / ENTRY- ELECTRICAL/LIGHTING-O.K.                                                      | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI    | LIVING/DINING ROOM- FLOORING-floor buckling in front of bathroom, see tape                   | Barwood<br>Flooring  | 24Apr09 | 60 |
| <u>23Feb09</u> | PDI    | LIVING/DINING ROOM- FLOORING: 1-paint on boards in front of bathroom,see tape                | Barwood<br>Flooring  | 24Apr09 | 60 |
| <u>23Feb09</u> | PDI    | LIVING/DINING ROOM- ELECTRICAL/LIGHTING-filter missing in fancoil unit                       | Lisi<br>Mechanical   | 24Apr09 | 60 |
| <u>23Feb09</u> | PDI    | LIVING/DINING ROOM- ELECTRICAL/LIGHTING: 1-thermostat showing code SF                        | Lisi<br>Mechanical   | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI    | LIVING/DINING ROOM- ELECTRICAL/LIGHTING: 1-thermostat showing code SF                        | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI    | LIVING/DINING ROOM- WINDOWS-marks and scratches around window, see tape                      | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI    | LIVING/DINING ROOM- WINDOWS: 1-excessive silicone window panel to right of windows, see tape | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI    | LIVING/DINING ROOM- WINDOWS: 2-ALUMINUM THRESHOLD loose, see tape                            | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI    | LIVING/DINING ROOM- CEILING-O.K.                                                             | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI    | LIVING/DINING ROOM- WALLS-O.K.                                                               | Amacon - PDI<br>- OK | 23Feb09 | 0  |

|                |     |                                                                                            |                   |          |     |
|----------------|-----|--------------------------------------------------------------------------------------------|-------------------|----------|-----|
| <u>23Feb09</u> | PDI | GUEST BEDROOM 1- WALLS-mark on wall opposite windows, see tape                             | Amacon Service    | 25Feb09  | 2   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 1- DOORS-door stop missing                                                   | Amacon Service    | 25Feb09  | 2   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 1- DOORS: 1-chip on front of door right side, see tape                       | Amacon Service    | 25Feb09  | 2   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 1- DOORS: 2-casing chipped right side, see tape                              | Amacon Service    | 25Feb09  | 2   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 1- FLOORING-gap at baseboard to right of window, see tape                    | Amacon Service    | 25Feb09  | 2   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 1- FLOORING: 1-T-CAP cracked and not flush, see tape                         | Barwood Flooring  | 24Apr09  | 60  |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 1- CEILING-O.K.                                                              | Amacon - PDI - OK | 23Feb09  | 0   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 1- CLOSET-O.K.                                                               | Amacon - PDI - OK | 23Feb09  | 0   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 1- ELECTRICAL/LIGHTING-light switch cover not flush, see tape                | Amacon Service    | 25Feb09  | 2   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 1- WINDOWS-glue around windows, see tape                                     | Amacon Service    | 25Feb09  | 2   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 1- WINDOWS: 1-mark on inside of sliding window, see tape                     | Amacon Service    | 25Feb09  | 2   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 2- WALLS-mark on right wall in front of window, see tape                     | Amacon Service    | 25Feb09  | 2   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 2- DOORS-door stop missing                                                   | Amacon Service    | 25Feb09  | 2   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 2- DOORS: 1-mark on bottom front and backside of door, see tape              | Amacon Service    | 25Feb09  | 2   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 2- FLOORING-CLEAN CARPET                                                     | Amacon Service    | 25Feb09  | 2   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 2- CEILING-O.K.                                                              | Amacon - PDI - OK | 23Feb09  | 0   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 2- CLOSET-doors missing                                                      | Amacon Service    | 08Sept09 | 197 |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 2- CLOSET-doors missing                                                      | JJ Home Products  | 08Sept09 | 197 |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 2- ELECTRICAL/LIGHTING-breaker schedule missing                              | DECC Electric     | 15Mar09  | 20  |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 2- WINDOWS-excess glue around windows, see tape                              | Amacon Service    | 25Feb09  | 2   |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 2- WINDOWS: 1-window stop not flush east facing window, right side, see tape | Amacon Service    | 25Jun09  | 122 |
| <u>23Feb09</u> | PDI | GUEST BEDROOM 2- WINDOWS: 1-window stop not flush east facing window, right side, see tape | Allan Windows     | 25Jun09  | 122 |
| <u>23Feb09</u> | PDI | MASTER BEDROOM- WALLS-DRYWALL DENTED below thermostat, see tape                            | Amacon Service    | 25Feb09  | 2   |
| <u>23Feb09</u> | PDI | MASTER BEDROOM- WALLS: 1-gap at bottom of j-mold right window, see tape                    | Amacon Service    | 25Feb09  | 2   |

|                |     |                                                                                            |                      |         |    |
|----------------|-----|--------------------------------------------------------------------------------------------|----------------------|---------|----|
| <u>23Feb09</u> | PDI | MASTER BEDROOM- DOORS-O.K.                                                                 | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | MASTER BEDROOM- FLOORING-O.K.                                                              | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | MASTER BEDROOM- CEILING-O.K.                                                               | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | MASTER BEDROOM- CLOSET-chipped casing, walk-in closet,<br>right side, see tape             | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | MASTER BEDROOM- ELECTRICAL/LIGHTING-thermostat<br>showing code SF, see tape                | Lisi<br>Mechanical   | 27Mar09 | 32 |
| <u>23Feb09</u> | PDI | MASTER BEDROOM- ELECTRICAL/LIGHTING: 1-filter and<br>back panel missing                    | Lisi<br>Mechanical   | 24Apr09 | 60 |
| <u>23Feb09</u> | PDI | MASTER BEDROOM- ELECTRICAL/LIGHTING: 2-overspray<br>paint on fire alarm silencer, see tape | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | MASTER BEDROOM- WINDOWS-glue and marks around<br>windows, see tape                         | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | MASTER BEDROOM- WINDOWS: 1-BALCONY SILL marked,<br>right side, see tape                    | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | MASTER BEDROOM- WINDOWS: 2-BALCONY SILL chipped,<br>see tape                               | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | MASTER BEDROOM- WINDOWS: 3-marks and scratches<br>around balcony door, see tape            | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | DEN- WALLS-chipped corner right wall, see tape                                             | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | DEN- FLOORING-gap in board, see tape                                                       | Barwood<br>Flooring  | 24Apr09 | 60 |
| <u>23Feb09</u> | PDI | DEN- FLOORING: 1-baseboard chipped, back wall, see tape                                    | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | DEN- CEILING-O.K.                                                                          | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | DEN- ELECTRICAL/LIGHTING-O.K.                                                              | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- WALLS-O.K.                                                                  | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- DOORS-outside casing chipped, see tape                                      | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- DOORS: 1-excessive gap top right corner,<br>see tape                        | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- DOORS: 2-wrong door hardware--no lock                                       | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- DOORS: 3-excessive gap top left corner<br>inside, see tape                  | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- DOORS: 4-door doesn't close properly                                        | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- DOORS: 5-door rubbing against casing on<br>left side                        | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- DOORS: 6-stain bottom of casing right side,<br>see tape                     | Amacon<br>Service    | 25Feb09 | 2  |

|                |     |                                                                                                |                   |         |    |
|----------------|-----|------------------------------------------------------------------------------------------------|-------------------|---------|----|
| <u>23Feb09</u> | PDI | MAIN BATHROOM- TUB-water from spigot when shower running                                       | Lisi Mechanical   | 24Apr09 | 60 |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- TOILET-O.K.                                                                     | Amacon - PDI - OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- CEILING-O.K.                                                                    | Amacon - PDI - OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- SINK-faucet loose, see tape                                                     | Lisi Mechanical   | 24Apr09 | 60 |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- COUNTERTOPS-left corner of backsplash needs silicone and is not flush, see tape | Megacity Granite  | 15Mar09 | 20 |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- COUNTERTOPS: 1-right corner at backsplash not flush, see tape                   | Megacity Granite  | 15Mar09 | 20 |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- VANITY CABINETS-O.K.                                                            | Amacon - PDI - OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- FLOORING-t-cap not flush, see tape                                              | Barwood Flooring  | 24Apr09 | 60 |
| <u>23Feb09</u> | PDI | MAIN BATHROOM- ELECTRICAL/LIGHTING-O.K.                                                        | Amacon - PDI - OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- WALLS-DRYWALL DENTED in front of vanity, see tape                            | Amacon Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- WALLS: 1-holes along front of tub along tiles, see tape                      | Amacon Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- WALLS: 2-mark below towel rack, see tape                                     | Amacon Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- DOORS-top front of door rough, see tape                                      | Amacon Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- DOORS: 1-mark around front door handle, see tape                             | Amacon Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- DOORS: 2-door stop missing                                                   | Amacon Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- DOORS: 3-lock missing                                                        | Amacon Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- DOORS: 4-chip upper rear left side, see tape                                 | Amacon Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- DOORS: 5-chips in casing, see tape                                           | Amacon Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- TUB-low water pressure                                                       | Lisi Mechanical   | 27Mar09 | 32 |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- TUB: 1-grout required top of accent tile, see tape                           | Amacon Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- TOILET-O.K.                                                                  | Amacon - PDI - OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- SINK-O.K.                                                                    | Amacon - PDI - OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- COUNTERTOPS-backsplash not flush, see tape                                   | Megacity Granite  | 15Mar09 | 20 |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- CEILING-O.K.                                                                 | Amacon - PDI - OK | 23Feb09 | 0  |

|                |     |                                                                                             |                      |         |    |
|----------------|-----|---------------------------------------------------------------------------------------------|----------------------|---------|----|
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- VANITY CABINETS-O.K.                                                      | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- FLOORING-O.K.                                                             | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | ENSUITE BATHROOM- ELECTRICAL/LIGHTING-exhaust fan<br>not working properly                   | York Sheet<br>Metal  | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | KITCHEN- FLOORING-O.K.                                                                      | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | KITCHEN- CABINETS-ADJUST CABINET doors above<br>microwave                                   | Cartier<br>Kitchens  | 04Mar09 | 9  |
| <u>23Feb09</u> | PDI | KITCHEN- CABINETS: 1-excessive hose inside cabinet under<br>sink                            | Cartier<br>Kitchens  | 04Mar09 | 9  |
| <u>23Feb09</u> | PDI | KITCHEN- CABINETS: 2-2nd drawer needs adjustment                                            | Cartier<br>Kitchens  | 04Mar09 | 9  |
| <u>23Feb09</u> | PDI | KITCHEN- CABINETS: 3-top drawer needs silicone stoppers                                     | Cartier<br>Kitchens  | 04Mar09 | 9  |
| <u>23Feb09</u> | PDI | KITCHEN- CABINETS: 4-cabinet to left of microwave not flush                                 | Cartier<br>Kitchens  | 04Mar09 | 9  |
| <u>23Feb09</u> | PDI | KITCHEN- CABINETS: 5-cabinet to right of fridge not flush                                   | Cartier<br>Kitchens  | 04Mar09 | 9  |
| <u>23Feb09</u> | PDI | KITCHEN- CABINETS: 6-excessive gap cabinet above<br>dishWASHER, see tape                    | Cartier<br>Kitchens  | 04Mar09 | 9  |
| <u>23Feb09</u> | PDI | KITCHEN- CABINETS: 7-excessive silicone on dishWASHER<br>gable, see tape                    | Cartier<br>Kitchens  | 04Mar09 | 9  |
| <u>23Feb09</u> | PDI | KITCHEN- COUNTERTOPS-excessive gap underside of<br>countertop at dishWASHER gable, see tape | Cartier<br>Kitchens  | 04Mar09 | 9  |
| <u>23Feb09</u> | PDI | KITCHEN- SINK-no hot water                                                                  | Lisi<br>Mechanical   | 27Mar09 | 32 |
| <u>23Feb09</u> | PDI | KITCHEN- APPLIANCE-O.K.                                                                     | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | KITCHEN- ELECTRICAL/LIGHTING-BULBS BURNED OUT                                               | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | KITCHEN- CEILING-O.K.                                                                       | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | KITCHEN- WINDOWS-mark to left of balcony door, see tape                                     | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | KITCHEN- WINDOWS: 1-ALUMINUM marked top panel to<br>right of balcony door                   | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | KITCHEN- WINDOWS: 2-excessive silicone along left side of<br>balcony door, see tape         | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | KITCHEN- BACKSPLASH-O.K.                                                                    | Amacon - PDI<br>- OK | 23Feb09 | 0  |
| <u>23Feb09</u> | PDI | KITCHEN- WALLS-marks on j-mold, see tape                                                    | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | LAUNDRY CLOSET- NOTE-please close secondary lint trap                                       | Amacon<br>Service    | 25Feb09 | 2  |
| <u>23Feb09</u> | PDI | LAUNDRY CLOSET- DOORS-O.K.                                                                  | Amacon - PDI<br>- OK | 23Feb09 | 0  |

|         |     |                                                |                   |         |   |
|---------|-----|------------------------------------------------|-------------------|---------|---|
| 23Feb09 | PDI | LAUNDRY CLOSET- WALLS-marks on walls, see tape | Amacon<br>Service | 25Feb09 | 2 |
|---------|-----|------------------------------------------------|-------------------|---------|---|

**Total Reported Deficiencies: 144 / Average Days Open: 16**Customer Info