

Grahme Walsh

From: Jim Hill [jimh@allanwindows.com]
Sent: February-20-12 9:14 AM
To: Grahme Walsh; Mark Fritz; Paul Garand
Subject: Fw: Elle

----- Original Message -----

From: Jim Hill
To: Sandra Valencia
Sent: Mon Feb 20 09:07:36 2012
Subject: Elle

Suite 1007. Follow up
Checked Dec 19/11

Excessive condensation on inside and outside at area's around corner posts Replaced failed s/u then drilled holes in both corners and pumped in foam spray inside corner took very little Amacon to caulk curb sill flashing leaving a couple of holes for drainage if any water enters into system

*Allan Windows
Elle 1007
- 21/02/2012
- Amacon to caulk
21/202/2012
u PROAD to
pass*