

AMACON

Friday, July 06, 2012

Alex Noble
3525 Kariya Drive #2806
Mississauga, ON L5B 0C2

RE: Expired Warranty

Alex Noble,

We have received your service request regarding item(s) that are listed by you to be defective. The material(s) and workman ship coverage provided by Tarion warranty expired on **February 22 .2012**

ITEM	LOCATION	DESCRIPTION	REPORT BY AMACON
3	Balcony Door	Weather Stripping is torn.	This item is not warrantable, one year work and materials. This item was not noted on PDI, 30 day form and or 1 year form.

For specific information on how to proceed, refer back to the Tarion Home Owner Manual or visit www.tarion.com Construction Performance Guidelines. As discussed in the Homeowner Manual components of your home are listed, it also includes guidelines on maintenance and repairs.

If after reviewing the information in the manual, you have any further questions please contact me, I'll be happy to discuss these maintenance tasks with you.

Sincerely,

Amacon Customer Care

ATTN

ANORADE

AMACON SERVICE REQUEST FORM
PLEASE MAIL, FAX OR SUBMIT ON-LINE
AMACON CONSTRUCTION LTD. ATTENTION: CUSTOMER CARE

TEL: 416-369-9069 FAX: 416-369-9068

www.amacon.com

NAME: ALEX NOBLEDEVELOPMENT NAME: ELLE CONDOMINIUMADDRESS: 3525 KARIYA DR. #2806RES.TEL: 905-241-3398 BUS.TEL: 905-306-8544CELL: 416-200-3356 FAX: _____DATE OF REQUEST: JULY 4TH / 2012

A copy of your request form will be given to and reviewed by an Amacon Customer Care Representative. Your request and any follow up that may be required will be co-ordinated by one of our Customer Care Representatives to ensure that your concerns are addressed.

Service Request:

1. Fix bedroom window - handle
mechanism is broken
2. Please provide paint sample OR
paint code & manufacturer
3. Please check weatherstripping at
bottom of balcony door - is torn
4. _____

Elle # 2806

Service Request #3 Weather
Stripping is torn.

Not warrantable.

Picture taken July 5th.

2012

