

Work Order

Warranty Services
Phone: (905) 232-4636
Fax: (905) 232-4637



Location: The Residences At Parkside Village - 2 - Suite: 3310
Today's Date: 25Jul13
Company: Amacon Customer Care - Site
Attention: Sandy Cardoso
Telephone: 905-232-4637
Fax:

Please Complete the following items:

Deficiency Number	Issue	Appt. Date/Time	Notes
49808	FOYER / ENTRY- CEILING~small hole in ceiling near overhead foyer light		- Group Assign
49809	LIVING/DINING ROOM- WINDOWS~marks on beauty cap at ceiling		- Group Assign
49810	LIVING/DINING ROOM- WINDOWS~touch up window trim to wall left and right side, scratch on window frame left window left edge		- Group Assign
49811	LIVING/DINING ROOM- WALLS~touch up baseboard and corner round below phone jack and counter overhang		- Group Assign
49812	LIVING/DINING ROOM- WALLS~seams in long wall right of window right of window, paint patches visible		- Group Assign
49813	MASTER BEDROOM- --touch up window trim to wall left and right side and at bulkhead above		- Group Assign
49814	MASTER BEDROOM- WALLS~wall seam visible on wall right of window at middle, black mark right of vent grill		- Group Assign