

Done

Adom.
Work Order




Warranty Services
Phone: (905) 232-4636
Fax: (905) 232-4637

Location: THE RESIDENCES AT PARKSIDE VILLAGE - TWO - Suite: 411
Today's Date: 02Nov16
Company: Amacon Customer Care - Site
Attention: Sandy Cardoso
Telephone:
Fax: (905) 232-4637

Please Complete the following items:

Deficiency Number	Issue		Appt. Date/Time	Notes
71258 Done	FOYER / ENTRY- WALLS~ther are black streaks to the right of the door	✓		
71259 Done	FOYER / ENTRY- DOORS~there are two black marks to the right of the lock on the doorframe	✓		
71260 Done	LIVING/DINING ROOM- WALLS~there are scuff marks to the left and below of balcony doors	✓		
71261 Done	LIVING/DINING ROOM- WALLS~there are paint chipping to the left of balcony doors	✓		
71262 Done	LIVING/DINING ROOM- WALLS~inconsistent caulking below the balcony door and below the windows	✓		
71263 Done	LIVING/DINING ROOM- WALLS~there is a scratch above electrical outlet below the 4 receptacle switches	✓		
71264 Done	MASTER BEDROOM- DOORS~purchaser feels that the door frames paint is chipping	✓		
71265 Done	MASTER BEDROOM- DOORS~outside of door	✓		



	frame is scratched on the left right beside electrical outlet	✓		<i>This page is</i> <i>Double checked</i> <i>only close ACC</i>
71266 <i>Trade</i>	MASTER BEDROOM-FLOORING~As you enter master bedroom there are black streaks on the carpet	✓	→	<i>Megacity Carpets.</i> <i>need cleaning</i>
71267 <i>Done</i>	MASTER BEDROOM-FLOORING~there are black streaks on carpet below phone jack	✓		
71268 <i>Done</i> <i>Trade</i> <i>04/11/16</i>	MASTER BEDROOM-CLOSET~purchaser feels that the closet doors have scratches. dirty and want them replaced	✓		<i>+ final clean.</i>
71269 <i>Done.</i>	MASTER BEDROOM-CLOSET~top right corner on the edge of closet frame is scratched	✓		
71271 <i>Done</i>	MASTER BEDROOM-WINDOWS~inconsistent caulking below the windows	✓		
71272 <i>Done</i>	DEN- WALLS~as you enter the den there are scuff marks on the lower middle of the left side	✓		
71273 <i>Done</i>	MAIN BATHROOM- --from the inside of the washroom top left corner of the door frame has holes	✓		
71274 <i>Done</i>	MAIN BATHROOM-DOORS~purchaser feels that the edge of the doors finishes is not smooth enough	✓		
71276 <i>Trade</i>	MAIN BATHROOM-TUB~tiles is scratched 3 feet up opposite side of the tub faucet	✓		<i>mega city tile</i>
71277 <i>Trade</i>	MAIN BATHROOM-TUB~tiles is scratched 3 feet up from the tub on the same side as the faucet			<i>grout missing.</i> <i>also</i> <i>mega city tile</i>
71278 ✓	MAIN BATHROOM-TUB~purchaser feels that			

	there is inconstant caulking around the brown tiles above the tub	✓		
71281	MAIN BATHROOM-SINK~purchaser feels that the faucet isn't caulked well enough	✓		
71282	MAIN BATHROOM-COUNTERTOPS~inconsistent caulking below the mirror	✓		
71283	MAIN BATHROOM-COUNTERTOPS~purchaser feels that there is glue on the right of the sink and towards the mirror	✓		
71292	LAUNDRY CLOSET-DOORS~there are indents above the lock on the outside perimeter of door	✓		

Date Completed: Nov 4/16 Amacon Customer Care Signature: Perry

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 232-4637.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Date: _____ Homeowner (or Homeowner Rep.) Signature: _____