



Warranty Services
Phone: (905) 232-4636
Fax: (905) 232-4637

Work Order

Location: THE RESIDENCES AT PARKSIDE VILLAGE - TWO - Suite: 412
Today's Date: 02Nov16
Company: Amacon Customer Care - Site
Attention: Sandy Cardoso
Telephone:
Fax: (905) 232-4637

Please Complete the following items:

Deficiency Number	Issue		Appt. Date/Time	Notes
71301 <i>Done</i>	LIVING/DINING ROOM-FLOORING~baseboards are stained to the left and right side of the guest bedroom	<i>X</i>		
71368 <i>Done</i> <i>03/11/16</i>	LIVING/DINING ROOM-WINDOWS~there are gaps between the window sills opposite side of the guest room but in the living room	<i>X</i>		
71303 <i>Done</i>	LIVING/DINING ROOM-WALLS~wall left to the guest bedroom door has uneven coat of paint	<i>X</i>		
71304 <i>Done</i>	LIVING/DINING ROOM-WALLS~there is a black streak 1 foot and 10 inches above central vacuum outlet	<i>X</i>		
71305 <i>Done</i>	LIVING/DINING ROOM-WALLS~there is a hole above central air vacuum outlet	<i>X</i>		
71306 <i>Done</i>	LIVING/DINING ROOM-WALLS~there is a dent 1 foot 3 inches away from phone jack right side of balcony windows	<i>X</i>		
71307 <i>Done</i>	GUEST BEDROOM 1-CLOSET~has black streaks on the lower back wall	<i>X</i>		
71308	GUEST BEDROOM 1-WINDOWS~below the	<i>X</i>		

DONE 3/11/16	windows there is inconsistency of caulking	✓		
71309 DONE 3/11/16	GUEST BEDROOM 1- WINDOWS~there is a crack top right corner of the window frame on the wall	✓		
71310 Done	MASTER BEDROOM- WALLS~as you enter there is a black mark on the wall beside the closet	✓		
71311 DONE	MASTER BEDROOM- DOORS~below door handle there are black marks	✓		
71312 Done	MASTER BEDROOM- FLOORING~baseboard on bottom right corner of the windows have a green mark above baseboard	✓		
71313 DONE 3/11/16	MASTER BEDROOM- FLOORING~there is a gap between the carpet and master bedroom washroom floors	✓		
71314 Done	DEN- WALLS~door frame on the left side of main bathroom has a pink stain	✓		
71315 Done	DEN- WALLS~there is a yellow mark opposite side of main bathroom	✓		
71316 Done	DEN- FLOORING~baseboards beside the washroom door frame to the left is missing paint on the edge	✓		
71317 DONE 3/11/16	ENSUITE BATHROOM- --purchaser feels that the shower rod is crooked	✓		
71323 DONE	KITCHEN- CABINETS~under the cabinet above the fridge there is chipped paint	✓		
71324 Done	KITCHEN- CABINETS~inconsistent paint above cabinets above micro wave	✓		

71325	KITCHEN- COUNTERTOPS~inconsiste nt caulking on the left side of the sink against the wall	✓		
return Done	71331 KITCHEN- WALLS~the wall to the left of the sink beside the gfi has yellow stains	✓		
return Done	71332 KITCHEN- WALLS~wall to the left of the fridge is chipped	✓		
Trade.	71336 KITCHEN- NOTE~fridge should not be protruding and flushed w/5h against the wall			graham to check about fridge

Already Double Traded - Only Close out ACC 8th

Date Completed: NOV 4/16 Amacon Customer Care Signature: Terry

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 232-4637.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Date: _____ Homeowner (or Homeowner Rep.) Signature: _____