

Done

AMACON

LIVE WELL

Warranty Services  
Phone: (905) 232-4636  
Fax: (905) 232-4637

Omar  
Work Order

Location: THE RESIDENCES AT PARKSIDE VILLAGE - TWO - Suite: 501  
Today's Date: 02Nov16  
Company: Amacon Customer Care - Site  
Attention: Sandy Cardoso  
Telephone:  
Fax: (905) 232-4637

Please Complete the following items:

Deficiency Number	Issue		Appt. Date/Time	Notes
71369 Done	FOYER / ENTRY- WALLS~paint chipped on wall on left of bathroom entrance door trim 6 ft up.. paint chipped on left door trim of bathroom entrance 5.5 ft up.	T2		
71371 Done	LIVING/DINING ROOM- WALLS~chipped wall to right of master bedroom entrance 5 ft up. missing paint under sliding balcony door.	T2		
71374 Done	MASTER BEDROOM- CLOSET~remove paint from top trim of closet doors.	T2		
71375 Done	BATHROOM 1st FLOOR- WALLS~paint door trim inside bathroom top right . wall chipped in corner on right side of door 3ft up.	T2		
71376 Done	ENSUITE BATHROOM- WALLS~paint cracked on top left door trim entrance to ensuite.	T2		
71379 <del>Track</del>	ENSUITE BATHROOM- DOORS~door not latching closed.	T2		

Date Completed: \_\_\_\_\_ Amacon Customer Care Signature: \_\_\_\_\_

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 232-4637.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Date: \_\_\_\_\_ Homeowner (or Homeowner Rep.) Signature: \_\_\_\_\_