



Warranty Services Phone: (905) 232-4636

Fax: (905) 232-4637



Location:

THE RESIDENCES AT PARKSIDE VILLAGE - TWO - Suite: 503

Today's Date:

01Nov16

Company:

Amacon Customer Care - Site

Attention:

Sandy Cardoso

Telephone: Fax:

(905) 232-4637

Please Complete the following items:

Deficiency Number	Issue		Appt. Date/Time	Notes
77203 Done	FOYER / ENTRY- CLOSET~rough discolored paint on wall inside closet on right side near sliding door.	W/		
71205 Done Tracks on floor	LIVING/DINING ROOM- WALLS~dirt on wall in 2 places left of windows. large chip on floor 4 ft to right of thermostate and 3 ft from wall.			*
71206 Donc	MASTER BEDROOM-WALLS~paint bubble on inside of door just right of handle. rough paint just above baseboard just right of door. extra paint on vinyl trim on left of window. crack in paint on corner edge of wall where it meets wall above window on left side.			
71207 Rona	MASTER BEDROOM- CLOSET~closet door paint chipped on left of handle.			
71208 Oone	BATHROOM 1st FLOOR- DOORS~door not latching closed.			
71211 Ogne	KITCHEN- WALLS~mark on wall on right side over stove. middle light bulb out. crack in paint on wall edge over cabinets. marks on wall edge to left of fridge 9 ft from floor.	V		

	paint cracked almost up to ceiling about 1 ft to the right of laundry starting 8 ft up.	
Date C	Completed: 0008/16 Amacon Customer Care Signature:	
Please time or appoint	e schedule your Service Department to complete work on the above Unit. Should no appoir date appear (below) on this form, it is your responsibility to arrange and adhere to the attment you have scheduled. Your service representative must have this form signed by hompletion. Please fax the signed form to our office (905) 232-4637.	
Failure to carry	e to comply with this request will give Amacon Developments (and it's group of companies) y out any and all repairs. All costs incurred will be applied to the Company listed above.) the right
Date:	Homeowner (or Homeowner Rep.) Signature:	