

AMACON

LIVE WELL

Warranty Services

Phone: (905) 232-4636

Fax: (905) 232-4637

Return Mike

Work Order

Location: THE RESIDENCES AT PARKSIDE VILLAGE - TWO - Suite: 504
 Today's Date: 02Nov16
 Company: Amacon Customer Care - Site
 Attention: Sandy Cardoso
 Telephone:
 Fax: (905) 232-4637

Please Complete the following items:

Deficiency Number	Issue	Appt. Date/Time	Notes
71518 PATCH PAINT DONE 11.7.16	FOYER / ENTRY- WALLS~mark on wall on right wall when facing door 6 ft up.	TZ	
71519 SAND PATCH PAINT DONE 11.7.16	FOYER / ENTRY- DOORS~paint patch visible on top door trim.	TZ	
71520 PATCH LADDER DONE 11.7.16	FOYER / ENTRY- CEILING~paint bubble line on lower ceiling above the left side of bathroom entrance.	TZ	
71521 SAND PATCH PAINT DONE 11.4.16	LIVING/DINING ROOM- WALLS~baseboard chipped below outlet left of window.	TZ	
71523 GRANT FIND BLUE PATCH DONE 11.7.16	GUEST BEDROOM 1- WALLS~blue paint patch on wall right of window in bedroom 3.		
71524 DONE 11.4.16	GUEST BEDROOM 2- ~paint on trim above closet.		where he took off paint...
71525 CAULK PATCH SAND PATCH PATCH LIGHT SWITCH BEDROOM SAND & PAINT WALL UNDER VENT AND PATCH DONE 11.7.16	GUEST BEDROOM 2- WALLS~crack in paint on wall just right of the top right blind bracket. paint chip on left side of bedroom light switch. rough paint below vent. cracked paint along vertical wall corner to left of windows.		

71527	<p>MAIN BATHROOM- WALLS~paint bubble on wall just left of outlet (paint on mirror edge just left of outlet. door trim has rough paint on top left. long crack visible between tiles and wall on left of shower.)</p>	✓		
71528	<p>MAIN BATHROOM- DOORS~rough paint patches on outside surface of door on left side half way up and 1 ft above that.</p>	✓		
71529	<p>MAIN BATHROOM- CEILING~scratch on ceiling 1 ft inside door.</p>	✓		
71530	<p>MAIN BATHROOM- FLOORING~paint on floor next to tub on left side.</p>	✓		
71534	<p>LAUNDRY CLOSET- NOTE~move washer to right to improve access to water shutoff.</p>	✓		
71536	<p>LAUNDRY CLOSET- DOORS~door not latching.</p>	✓		

dated: Nov 9th 2016

e: Terrey

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Homeowner (or Homeowner Rep.) Signature: _____