MKE

Work Order

AMACON

Warranty Services Phone: (905) 232-4636 Fax: (905) 232-4637

Location:

THE RESIDENCES AT PARKSIDE VILLAGE - TWO - Suite: 507

Today's Date:

02Nov16

Company:

Amacon Customer Care - Site

Attention:

Sandy Cardoso

Telephone: Fax:

(905) 232-4637

Please Complete the following items:

	Deficiency Number	Issue	Appt. Date/Time	Notes
	ı	LIVING/DINING ROOM- WINDOWS~caulking gap most of the way up on the left of balcony door, dent and chip on bottom left corner of balcony door.		Dent Not Done Accom windows TRADE
0000	71538CAMIK PATCH SAWD & PAINT	LIVING/DINING ROOM- WALLS~wall cracked by the pull chain bracket left of balcony door. chip in the wall just above baseboard left of the windows. rough paint on right inner edge of master bedroom door trim 6 ft up opposite hinge side.	/ pue	Dus
	71539 7154D	MASTER BEDROOM- FLOORING~carpets are dirty.		
シスプン	715405+ND PAINT DOWE	DEN- WALLS~paint blob above the right closet door trim in den. paint chipped on wall corner edge to the right of den closet, 5 ft up.		More
70%	71541 5AND	MAIN BATHROOM- WALLS~chip on the door trim by the door latch hole.		Moure
Son	71542 MW	MAIN BATHROOM- DOORS~squeeky door hinge.		me.
* 1.40	71543 CANIK C	MAIN BATHROOM- COUNTERTOPS~not		

4					
Dar		enough caulking on left edge of counter against wall on left facing sink.			me.
egacity -	71544 GOOF. WONTE	MAIN BATHROOM- FLOORING~long black marks on 1st, 2nd and 3rd tiles from door.			
11.4.16 Done	71545 (AULK	KITCHEN-COUNTERTOPS~2 scratches on edge of countertop above cabinet door to the right of sink. caulking missing on island between countertop and wall. black lines on countertop above dishwasher.			Coulting NOT DONES
DONE 1107.16	71547 CAUIK	KITCHEN- BACKSPLASH~caulking missing from left edge of backsplash.			Not Dane
11.2.16 Done	71548 PATCH	LAUNDRY CLOSET- DOORS~chipped door on outside, by the lower hindge. chipped door on inside surface, upper right side.			Journ
5.50 m	71550 PATEH DONE GOOF	LAUNDRY CLOSET- WALLS~chips on door trim underside of top trim. 2 chips on left door trim 5 ft up. dark lines on wall right side of washer and 2 tiles back.			Jon.
A. 16 Dove	71552 DONE	STORAGE- FLOORING~laundry room floor has paint 3rd tile from door on 1st tile on door hitch side of closet.			Jona de la companya della companya d
~~	Date Complet	ted: M / Amacor	n Custome	r Care Signa	ature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 232-4637.

te:	Homeowner (or Homeowner Rep.) Signature:					

page 3 / 3

Printed On November 02, 2016