

done



Warranty Services
Phone: (905) 232-4636
Fax: (905) 232-4637

RAJ.
Work Order

Location: THE RESIDENCES AT PARKSIDE VILLAGE - TWO - Suite: 509
Today's Date: 02Nov16
Company: Amacon Customer Care - Site
Attention: Sandy Cardoso
Telephone:
Fax: (905) 232-4637

Please Complete the following items:

| Deficiency Number | Issue | | Appt. Date/Time | Notes |
|-------------------|--|---|-----------------|--------------------|
| 71380 done | FOYER / ENTRY- WALLS~wall in front of the entrance has a black mark | ✓ | | ✓ |
| 71382 done | LIVING/DINING ROOM- FLOORING~baseboard below fan coil unit has a hole on the base shoe trim | ✓ | | ✓ |
| 71384 done | LIVING/DINING ROOM- FLOORING~baseboard corner to the right of fan coil unit is chipped | ✓ | | ✓ |
| 71385 done | LIVING/DINING ROOM- FLOORING~south east corner under baseboard shoe trim there is a gap between the floors and trim | ✓ | | ✓ |
| 71404 done | LIVING/DINING ROOM- ELECTRICAL/LIGHTING~circular object not installed properly above fan coil vent | ✓ | | TRADE sprinkler |
| 71387 done | LIVING/DINING ROOM- WALLS~wall above baseboard has holes under the balcony door frames on the bottom left | ✓ | | ✓ |
| 71388 done | LIVING/DINING ROOM- WALLS~wall on north west bottom corner has a crack beside balcony window | ✓ | | ✓ |
| 71389 | MASTER BEDROOM- WALLS~there is a dent in | | | ✓ |

| | | | | |
|---------------|---|---|--|------------------|
| done | wall on the south east beside electrical panel | ✓ | | ✓ |
| 71391 done | MAIN BATHROOM- DOORS~door stopper not installed properly | ✓ | | ✓ |
| 71392 done | MAIN BATHROOM- TUB~brown wall tiles have inconsistent caulking beside the tub | ✓ | | ✓ |
| 71393 done | MAIN BATHROOM- VANITY CABINETS~toe kick has paint on it | ✓ | | ✓ |
| 71398 done | KITCHEN- CABINETS~cabinet door under the sink to the far left has a scratch on top let corner | ✓ | | ✓ |
| 71402 done | KITCHEN- ELECTRICAL/LIGHTING~To the right of the fridge, the left light switch does not work | ✓ | | outlet switch. ✓ |
| 71403 done | KITCHEN- WALLS~wall to the left of the sink has a bump above the caulking | ✓ | | ✗ |

Date Completed: _____

Amacon Customer Care Signature: _____

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 232-4637.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Date: _____

Homeowner (or Homeowner Rep.) Signature: _____