

Done

Return

Adam



LIVE WELL

Warranty Services
Phone: (905) 232-4636
Fax: (905) 232-4637

Work Order

Location: THE RESIDENCES AT PARKSIDE VILLAGE - TWO - Suite: 510
Today's Date: 02Nov16
Company: Amacon Customer Care - Site
Attention: Sandy Cardoso
Telephone:
Fax: (905) 232-4637

Please Complete the following items:

Deficiency Number	Issue		Appt. Date/Time	Notes
71418 <i>DONE</i> muddled	FOYER / ENTRY- WALLS~there is paint from the door on top of the door rail on the wall			✓
71419 <i>DONE</i> muddled	FOYER / ENTRY- DOORS~door frame from the inside has bubbles on the left and right side			✓
71420 <i>DONE</i>	FOYER / ENTRY- DOORS~top of door rail has paint inconsistencies			✓
71424 <i>Done</i>	LIVING/DINING ROOM- ELECTRICAL/LIGHTING~to the left of the master bedroom door frame the right side of the two way switch does not function			<i>Outlet switch</i> - maybe switch for extra ceiling junction box? ✓
71425 <i>Done</i> muddled	LIVING/DINING ROOM- WALLS~wall to the left of closet has bubbly paint			✓
71429 <i>Done</i> muddled	LIVING/DINING ROOM- WALLS~wall to the left of closet has a dent at lower bottom			✓
71430 <i>Done</i>	MASTER BEDROOM- DOORS~top rail of the door is not smooth			✓
71432 <i>Done</i> muddled	MASTER BEDROOM- DOORS~bottom right corner below door hinges is chipped			✓

71434 DONE muddled	MASTER BEDROOM- DOORS~paint to the left of door handle is chipped			✓
71435 DONE muddled	MASTER BEDROOM- DOORS~the right leg/jamb of the door frame is not smooth			✓
71436 Trade	MASTER BEDROOM- FLOORING~there is a stain on the carpet all over			✓
71437 DONE	MASTER BEDROOM- CLOSET~there is paint on the on the valance	12.	✓ Not	DONE
71438 Done	MASTER BEDROOM- CLOSET~bottom of closet shelf is dirty on the right			✓
71439 DONE	MASTER BEDROOM- ELECTRICAL/LIGHTING~ve nt in room is not properly installed			✓
71440 DONE	MASTER BEDROOM- WINDOWS~caulking around window is dirty			✓
71442 Trade	MAIN BATHROOM- DOORS~lock on door does not function			- pin doesn't catch when door is closed
71443 DONE 07/11/16	MAIN BATHROOM- DOORS~left of door handle has chipped paint			✓
71444 07/11/16 DONE	MAIN BATHROOM- DOORS~threshold trim has glue on it			✓
71446 07/11/16 DONE	MAIN BATHROOM- DOORS~threshold trim has scratches			✓
71448 done muddled	MAIN BATHROOM- DOORS~top right corner of door frame is chipped			✓
71450 done muddled	MAIN BATHROOM- DOORS~there is a dent on the left leg/jamb near the bottom			✓
71451	MAIN BATHROOM-			

Done needed	DOORS~the leg/jamb paint has inconsistencies on both sides				✓
71455 Done needed	MAIN BATHROOM-DOORS~the right leg/jamb has dents				✓
71456 Done needed	MAIN BATHROOM-DOORS~the right leg/jamb has scratches				✓
71458 Done needed	MAIN BATHROOM-DOORS~the right leg/jamb has paint inconsistencies				✓
71453 Done	MAIN BATHROOM-DOORS~the doors squeak				✓
71461 Done	MAIN BATHROOM-TUB~bath tub is scratched on the inside of the tub near the bottom				✓
71463 Done	MAIN BATHROOM-TUB~there is a scratch on bath tub on the top of tub opposite side of the toilet				✓
71465 Done	MAIN BATHROOM-ELECTRICAL/LIGHTING~exhaust fan not installed properly has gaps				✓
71469 Done	LAUNDRY CLOSET--washer and dryer do not turn on				✓
71470 Done	STORAGE--top of closet valance has paint on it				✓
71471 Done	STORAGE--the shelf in closet is dirty				✓
71472 Done	STORAGE--above the valance below the wall has paint inconsistencies				✓

Date Completed: 11/16

Amacon Customer Care Signature: [Signature]

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the

appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 232-4637.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Date: _____ Homeowner (or Homeowner Rep.) Signature: _____