



CONSTRUCTION SUMMARY

1N - 3 - The Barossa 6 (S38-6) Elev C

Extras at Time of Sale

Note:

CEILINGS

Inv.401 1 - CEILINGS - SMOOTH CEILINGS THROUGHOUT MAIN AND SECOND FLOOR

Line2986 Note:

20Jun21 / 9Sep21

CONSTRUCTION

Inv.401 1 - DELETE RAILING ON MAIN FLOOR AND CLOSE OF THE WALL AS PER SKETCH #1
RELOCATE EXISTING BASEMENT DOOR - AS PER SKETCH # 2

Line2977 Note:

20Jun21 / 9Sep21

HEATING AND AIR CONDITIONING

Inv.401 1 - HEATING AND AIR CONDITIONING - 13 SEER AIR CONDITIONER - 3 TON

Line2981 Note:

20Jun21 / 9Sep21

PAINT AND STAIN

Inv.401 1 - PAINT AND STAIN - WROUGHT IRON STAIRCASE - STAIN STAIRCASE TO MATCH

Line2984 Note:

20Jun21 / 9Sep21

PLUMBING

Inv.401 1 - ADDITIONAL LAUNDRY ROUGH IN - AS PER SKETCH IN THE BASEMENT # 3

Line2976 Note:

20Jun21 / 9Sep21

STAIRS AND RAILING

Inv.401 1 - STAIRS AND RAILING - WROGHT IRON UPGRADE 1

Line2983 Note:

20Jun21 / 9Sep21

WINDOWS - BASEMENT


Inv.401 2 - BASEMENT WINDOW - 30 X 30 - AS PER SKETCH

Line2980 Note:

20Jun21 / 9Sep21


BAROSSA 6

lot 1




Ground Floor
Elevation A

BAROSSA 6 *Set 1*



Second Floor
Elevation A

BAROSSA - 6 *dot 1*



Basement
Elevation A