

## Soil Engineers Ltd.

CONSULTING ENGINEERS

#### GEOTECHNICAL • ENVIRONMENTAL • HYDROGEOLOGICAL • BUILDING SCIENCE


100 NUGGET AVENUE, TORONTO, ONTARIO M1S 3A7 • TEL: (416) 754-8515 • FAX: (416) 754-8516

BARRIE MISSISSAUGA **OSHAWA** NEWMARKET GRAVENHURST PETERBOROUGH HAMILTON TEL: (905) 542-7605 TEL: (905) 440-2040 TEL: (705) 721-7863 TEL: (905) 440-2040 TEL: (905) 853-0647 TEL: (705) 684-4242 TEL: (905) 777-7956 FAX: (705) 721-7864 FAX: (905) 542-2769 FAX: (905) 725-1315 FAX: (416) 754-8516 FAX: (705) 684-8522 FAX: (905) 725-1315 FAX: (905) 542-2769 .

Inspection No. 70

## Lots 15 and 16 - Cranbrook Crescent

- The inspected footing subgrade is capable of sustaining a Maximum Allowable Soil Pressure of 150 kPa.
- The layout, size of strip footing and column pads of the dwellings are in general conformance with the approved permit drawing.



Gold Park Homes Inc.

Attention: Mr. Michael Cipriano

REFERENCE NO. 1608±C052

DATE: November 24, 2016

PROJECT:

Residential Subdivision Gold Park Homes at Kleinburg Glen Baron Street and Algoma Drive City of Vaughan

**JOB DESCRIPTION:** 

Footing Suibgrade Inspection

**DATE OF INSPECTION:** November 1, 2016

INSPECTOR: Jalal Fahimi, C.E.T.

DESIGNED SOIL PRESSURE:

RECOMMENDED MAXIMUM ALLOWABLE SOIL PRESSURE FOR INSPECTED SUBGRADE: 150 kPa

AS-BUILT ELEVATION:

As recorded by site superintendent

WATER CONDITION:

Moist

**DESCRIPTION OF INSPECTED SUBGRADE:** 

Compact silty sand till

METHOD OF INSPECTION:

Rod probe and visual

**SUBGRADE:** 

Approved for 150 kPa

GIVEN TO:

Bruno

1 kPa = 20.89 psf

The footings and foundation walls must be protected against frost action at all times. (05/91)



# Soil Engineers Ltd.

CONSULTING ENGINEERS

## GEOTECHNICAL • ENVIRONMENTAL • HYDROGEOLOGICAL • BUILDING SCIENCE

100 NUGGET AVENUE, TORONTO, ONTARIO M1S 3A7 • TEL: (416) 754-8515 • FAX: (416) 754-8516

BARRIE	MISSISSAUGA	OSHAWA	NEWMARKET	GRAVENHURST	PETERBOROUGH	HAMILTON
TEL: (705) 721-7863	TEL: (905) 542-7605	TEL: (905) 440-2040	TEL: (905) 853-0647	TEL: (705) 684-4242	TEL: (905) 440-2040	TEL: (905) 777-7956
FAX: (705) 721-7864	FAX: (905) 542-2769	FAX: (905) 725-1315	FAX: (416) 754-8516	FAX: (705) 684-8522	FAX: (905) 725-1315	FAX: (905) 542-2769

Inspection No. 99

## Lots 15 and 16 - Cranbrook Crescent

- The inspected footing subgrade is capable of sustaining a Maximum Allowable Soil Pressure of 150 kPa.
- The layout and size of the strip footings and column pads of the dwellings are in general conformance with the approved permit drawing.

SOIL ENGINEERS LTD.

Dennis Lai, P.Eng. DL:vk



Gold Park Homes Inc.

Attention: Mr. Michael Cipriano

REFERENCE NO. 1608-C052

DATE: January 5, 2017

## PROJECT:

Residential Subdivision Gold Park Homes at Kleinburg Glen Baron Street and Algoma Drive Cit of Vaughan

#### JOB DESCRIPTION:

Footing Subgrade Inspection

DATE OF INSPECTION: November 1, 2016

INSPECTOR: Jalal Fahimi, C.E.T.

## DESIGNED SOIL PRESSURE:

RECOMMENDED MAXIMUM ALLOWABLE SOIL PRESSURE FOR INSPECTED SUBGRADE: 150 kPa

#### AS-BUILT ELEVATION:

As recorded by site superintendent

#### WATER CONDITION:

Moist

## DESCRIPTION OF INSPECTED SUBGRADE:

Compact silty sand till

## METHOD OF INSPECTION:

Visual and rod probe

#### SUBGRADE:

Approved for 150 kPa

## GIVEN TO:

Bruno

1 kPa = 20.89 psf The footings and foundation walls must be protected against frost action at all times.