

Soil Engineers Ltd.

CONSULTING ENGINEERS

GEOTECHNICAL • ENVIRONMENTAL • HYDROGEOLOGICAL • BUILDING SCIENCE

100 NUGGET AVENUE, TORONTO, ONTARIO M1S 3A7 • TEL: (416) 754-8515 • FAX: (416) 754-8516


BARRIE TEL: (705) 721-7863 FAX: (705) 721-7864 MISSISSAUGA TEL: (905) 542-7605 FAX: (905) 542-2769 OSHAWA TEL: (905) 440-2040 FAX: (905) 725-1315 NEWMARKET TEL: (905) 853-0647 FAX: (416) 754-8516 GRAVENHURST TEL: (705) 684-4242 FAX: (705) 684-8522 PETERBOROUGH TEL: (905) 440-2040-FAX: (905) 725-1315 HAMILTON TEL: (905) 777-7956 FAX: (905) 542-2769

Inspection No. 85

Lots 89 and 90 - Cranbrook Crescent

- The inspected footing subgrade is capable of sustaining a Maximum Allowable Soil Pressure of 150 kPa.

The layout, size of strip footings and column pads of the dwellings are in general conformance with the approved permit drawing.



Gold Park Homes Inc.

Attention: Mr. Michael Cipriano

REFERENCE NO. 1608-C052

DATE: November 24, 2016

PROJECT:

Residential Subdivision Gold Park Homes at Kleinburg Glen Baron Street and Algoma Drive City of Vaughan

JOB DESCRIPTION:

Footing Subgrade Inspection

DATE OF INSPECTION: November 14, 2016

INSPECTOR: Jalal Fahimi, C.E.T.

DESIGNED SOIL PRESSURE:

RECOMMENDED MAXIMUM ALLOWABLE SOIL PRESSURE FOR INSPECTED SUBGRADE: 150 kPa

AS-BUILT ELEVATION:

As recorded by site superintendent

WATER CONDITION:

Moist

DESCRIPTION OF INSPECTED SUBGRADE:

Compact silty sand till

METHOD OF INSPECTION:

Rod probe and visual

SUBGRADE:

Approved for 150 kPa

GIVEN TO:

Bruno

1 kPa = 20.89 psf

The footings and foundation walls must be protected against frost action at all times. (05/91)



Soil Engineers Ltd.

CONSULTING ENGINEERS

GEOTECHNICAL • ENVIRONMENTAL • HYDROGEOLOGICAL • BUILDING SCIENCE

100 NUGGET AVENUE, TORONTO, ONTARIO M1S 3A7 • TEL: (416) 754-8515 • FAX: (416) 754-8516

BARRIE TEL: (705) 721-7863 FAX: (705) 721-7864 MISSISSAUGA TEL: (905) 542-7605 FAX: (905) 542-2769 OSHAWA TEL: (905) 440-2040 FAX: (905) 725-1315 NEWMARKET TEL: (905) 853-0647 FAX: (416) 754-8516 GRAVENHURST TEL: (705) 684-4242 FAX: (705) 684-8522

Attention: Mr. Michael Cipriano

REFERENCE NO. 1608-C052

Gold Park Homes Inc.

DATE: January 5, 2017

PETERBOROUGH TEL: (905) 440-2040 FAX: (905) 725-1315 HAMILTON TEL: (905) 777-7956 FAX: (905) 542-2769

Inspection No. 112

Lots 89 and 90 - Cranbrook Crescent

- The inspected footing subgrade is capable of sustaining a Maximum Allowable Soil Pressure of 150 kPa.
- The layout and size of the strip footings and column pads of the dwellings are in general conformance with the approved permit drawing.

PROJECT:

Residential Subdivision Gold Park Homes at Kleinburg Glen Baron Street and Algoma Drive Cit of Vaughan

JOB DESCRIPTION: Footing Subgrade Inspection

DATE OF INSPECTION: November 14, 2016

INSPECTOR: Jalal Fahimi, C.E.T.

DESIGNED SOIL PRESSURE:

RECOMMENDED MAXIMUM ALLOWABLE SOIL PRESSURE FOR INSPECTED SUBGRADE: 150 kPa

AS-BUILT ELEVATION:
As recorded by site superintendent

WATER CONDITION: Moist

DESCRIPTION OF INSPECTED SUBGRADE: Compact silty sand till

METHOD OF INSPECTION: Visual and rod probe

SUBGRADE: Approved for 150 kPa

GIVEN TO: Bruno

1 kPa = 20.89 psf The footings and foundation walls must be protected against frost action at all times.

SOIL ENGINEERS LTD.

DEY. LAN

PROFESSIONAL

Dennis Lai, P.Eng. DL:vk