



Pre Delivery Vendor Number: 45477 Enrollment: 2226402

Purchaser Name: Vladimir DJURIC Inspection Project: Rodeo Drive Condominiums

Vesna DJURIC

Phone Number: (647) 388-6157

Address: 20 ONeill Road Page 1 of 3 Inspector: Tom Haliburton Municipality: Toronto

Inspection Date: October 28, 2022

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

• Windows, interior and exterior doors. Door locks

Suite / Building: 527 / D South

- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

GENERAL		
NOTE	NO WATER - PLUMBING UNTESTED	
MAIN BATHROOM		
TUB	SHOWER ROD MISSING	
TUB	CAULKING MISSING AROUND SHOWER	
TUB	EXCESS GROUT ON SHOWER FLOOR	
NOTE	ERV COVER MISSING	
NOTE	ERV SWITCH MISSING	
LIVING/DINING ROOM		
NOTE	2 HEAT PUMP COVERS MISSING	
NOTE	2 THERMOSTATS MISSING	
WINDOWS	SCREEN DOOR MISSING	
WINDOWS	BALCONY DOOR STICKING	
BEDROOM 2		
WINDOWS	WINDOW SCREEN MISSING	
WINDOWS	SCRATCH ON WINDOW CASING BELOW CRANK AT GREEN DOT	
CLOSET	PAINT TOUCH UP AT SPRINKLER IN CLOSET	
FLOORING	PAINT OVERSPRAY ON FLOOR	
KITCHEN		
APPLIANCE	MICROWAVE MISSING	
CABINETS	HOOD FAN COVER DOES NOT FIT	
CABINETS	REMOVE STICKER GLUE ON FRIDGE PANEL	
CABINETS	KICKPLATE TOO FAR IN ON RIGHT SIDE. FASTENER SHOWING	
CABINETS	ALIGN FRIDGE & FREEZER DOORS	





Enrollment: 2226402

Purchaser Name: Vladimir DJURIC

Vesna DJURIC

Phone Number: (647) 388-6157

Inspector: Tom Haliburton

Pre Delivery Inspection

Page 2 of 3

Vendor Number: 45477

Project: Rodeo Drive Realty Inc

Suite / Building: 527 / D South

Municipality: Toronto

Address: 20 ONeill Road

Inspection Date: October 28, 2022

KITCHEN		
CEILING	ELECTRICAL HOLE IN CEILING BESIDE TRACK LIGHT	
DEN		
WALLS	PAINT TOUCH UP BEHIND DOOR	
WALLS	4 PAINT TOUCH UPS AS FLAGGED	
LAUNDRY CLOSET		
WALLS	PAINT TOUCH UP RIGHT WALL AS FLAGGED	
WALLS	PAINT TOUCH UP ABOVE CLOSET DOORS INSIDE CLOSET	
BEDROOM 1		
ELECTRICAL/LIGHTING	ELECTRICAL PANEL NOT LABELED	
CLOSET	PAINT OVERSPRAY ON FLOOR	
DOORS	SCREEN DOOR MISSING	
DOORS	BALCONY DOOR STICKING	
WINDOWS	MARK ON MIDDLE OF BALCONY DOOR FRAME AT GREEN DOT	
ENSUITE		
ELECTRICAL/LIGHTING	EXHAUST FAN NOT OPERATING	
TUB	CAULKING MISSING AROUND TUB	
TUB	SHOWER ROD MISSING	
DOORS	DOOR CASING DAMAGED AT BOTTOM BEHIND DOOR AT GREEN DOT	
DOORS	PAINT TOUCH UP ON DOOR AS FLAGGED	
FLOORING	GROUT GAPS AT BOTTOM OF DOOR CASINGS AT GREEN DOTS BROKEN	
FOYER CLOSET		
CLOSET	FLOOR GAP AT LEFT CORNER OF CLOSET DOORS AT GREEN DOT	





Enrollment: 2226402

Purchaser Name: Vladimir DJURIC

Vesna DJURIC

Phone Number: (647) 388-6157

Inspector: Tom Haliburton

Pre Delivery Inspection

Page 3 of 3

Vendor Number: 45477

Project: Rodeo Drive Realty Inc

Suite / Building: 527 / D South

Municipality: Toronto

Address: 20 ONeill Road

Inspection Date: October 28, 2022

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION. IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Vladimir DJURIC Vesna DJURIC

Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Purchaser's Signature

Tom Haliburton

Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature

Date (YYYY/MM/DD) 2022/10/28 October 28, 2022