Enrollment:

Purchaser Name: Kenton TAYLOR

Phone:

Closing Date: July 16, 2021

Inspector: Chris Bergman

Ormel

PDI

Vendor/Builder No.: 39348

Vendor: Lormel Developments (Bradford) Ltd

Lot/Phase: 124 / 2

51M-1087

Address: 183 Chelsea Crescent

Municipality: Town of Bradford West Gwillimbury

Inspection Date: July 09, 2021

Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- · Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

GENERAL COMMENTS			
NOTE:	TOUCH UPS REQUIRED THROUGH OUT AS INDICATED		
	CAULK BATHROOM ACCESSORIES		
STAIRS			
NOTE:	APPLY FINAL CLEAR COAT.		
FOYER/HALL			
FRONT DOORS	INSTALL DEADBOLT.		
MASTER ENSUITE BATH			
FAUCETS/PLUMBING	INSTALL FAUCET AND DRAINS.		
MASTER BEDROOM			
NOTE:	LATCH MISSING TOP OF MAIN DOOR.		
WALK IN CLOSET	PAINT TRAP DOOR IN CLOSET		
UPPER HALL			
NOTE:	INSTALL DOOR ON LININE CLOSET.		
SHARED ENSUITE			
NOTE:	INSTALL TOILET PAPER HOLDER.		
POWDER ROOM			
MIRROR	REPAIR DAMAGED MIRROR.		
EXTERIOR SEASONAL			
BRICKS	CHIPPED BRICK AT BACK OF HOUSE. NORTH EAST CORNER.		
PAINT	PAINT FRONT DOORS AND GARAGE DOORS.		
	PAINT LINTELS.		
NOTE:	FRAME DAMAGED AT BACK WINDOW BASEMENT.		

Enrollment:

Purchaser Name: Kenton TAYLOR

Phone Res: Phone Bus:

Closing Date: July 16, 2021 Inspector: Chris Bergman

Vendor / Builder: 39348

Project: Lormel Developments (Bradford) Ltd

Lot / Phase: 124 / 2 Plan: 51M-1087

Address: 183 Chelsea Crescent

Municiaplity: Town of Bradford West Gwillimbury Inspection Date: July 09, 2021

Page 2 of 2

REPLACE DAMAGED TOILET PAPER HOLDER.		
NSTALL ROD IN CLOSET.		
REPAIR STAIN AND FINAL COAT ON STAIRS.		
INSTALL SINK DRAIN.		
TIGHTEN PLUG INSIDE CABINET.		
2	ISTALL ROD IN CLOSET. EPAIR STAIN AND FINAL COAT ON STAIRS. INSTALL SINK DRAIN.	ISTALL ROD IN CLOSET. EPAIR STAIN AND FINAL COAT ON STAIRS. INSTALL SINK DRAIN.

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Kenton TAYLOR

Purchaser's Signature Purchaser's Name (print) Purchaser's Name (print) Purchaser's Signature

Chris Bergman

Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature

Date (YYYY/MM/DD) 2021/07/09 July 09, 2021