Enrollment:

Purchaser Name: Franco CRISOSTIMO

Jennifer CRISOSTIMO

Phone: (647) 463-8600

Phone:

Closing Date: July 28, 2021

Inspector: Chris Bergman



Quality Control

Vendor/Builder No.:

Vendor: Lormel Developments (Bradford) Ltd

Lot/Phase: Part 3, Block 164 / 2A Address: 283 Chelsea Crescent

Municipality:

Inspection Date: July 15, 2021

Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- · Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- · Bathroom accessories if provided
- . Mirrors, counter tops and cabinetry
- · Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- . Interior finished and trim carpentry
- · Hot water heater, if provided (not rental)
- · Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- · Faucets: Kitchen, bathroom, laundry room
- · Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- · Gas fireplaces, incl.circulation fans, if provided
- · Heat Recovery Ventilation system, if provided
- Heating system
- · Hot water heater, if provided (not rental)
- · Air conditioning system, if provided and if conditions permit

GENERAL COMMENTS	/		
NOTE:	VOUCH UPS REQUIRED THROUGH OUT AS INDICATED		
	WISTALL AIR REGISTERS THROUGHOUT		1
	MSTALL CENTRAL VAC OUTLETS	<u> </u>	7 <u>2 - </u>
MASTER BEDROOM			
WALLS/DOORS	INSTALL FRENCH DOOR LATCH.		
BASEMENT			
STAIRS	PAINT STAIRS AND HANDRAILS		
LAUNDRY ROOM			
SINK/FAUCET/PLUMBING	INSTALL TUB AND FAUCET.		************
KITCHEN	,		
SINK/FAUCET/PLUMBING	NSTALL FAUCET		
CABINETS	KICKPLATE MISSING.	8-1	
EXTERIOR SEASONAL	,		
PAINT	PAINT FRONT AND GARAGE DOORS.		
	PAINT LINTELS. NOT DONE		
MASTER ENSUITE BATH			
FAUCETS/PLUMBING	NSTALL FAUCETS	MICHAEL MANAGER	Zaramanna mas
MAIN BATHROOM	1		
FAUCETS/PLUMBING	NSTALL FAUCET.		
BEDROOM #2	/		
FLOORING	CHIP TO FLOOR. TOUCH SCRATCH IN 3RD BEDROOM AND HALLWAY BY KITCHEN.		
STAIRS			
NOTE:	STAIN TRIM AT BOTTOM OF STAIRS A LOS		

Enrollment:

Date (YYYY/MM/DD)

Purchaser Name: Franco CRISOSTIMO

Jennifer CRISOSTIMO

2021/07/15

Phone Res: (647) 463-8600

Phone Bus:

Closing Date: July 28, 2021 Inspector: Chris Bergman

Quality Control

Vendor / Builder:

Project: Lormel Developments (Bradford) Ltd

Lot / Phase: Part 3, Block 164 / 2A

Plan:

Address: 283 Chelsea Crescent

Municiaplity:

Inspection Date: July 15, 2021

Page 2 of 2

1-1-1		
POWDER ROOM	/	
ELECTRICAL/LIGHTING	SWITCH PLATE COVER MISSING	

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. Franco CRISOSTIMO Jennifer CRISOSTIMO Purchaser's Signature Purchaser's Name (print) Purchaser's Name (print) Purchaser's Signature Chris Bergman Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature

July 15, 2021