Enrollment:

Purchaser Name: Ryan CHANDOO

Stephanie CHANDOO

 Phone:
 (647) 225-8021

 Phone:
 (647) 980-3225

 Closing Date:
 June 28, 2021

 Inspector:
 Chris Bergman



PDI

Vendor/Builder No.: 39348

Vendor: Lormel Developments (Bradford) Ltd

Lot/Phase: 106 / 2

51M-1087

Address: 255 Chelsea Crescent

Municipality: Town of Bradford West Gwillimbury

Inspection Date: July 07, 2021

## Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- · Bathroom accessories if provided
- · Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- · Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

GENERAL COMMENTS			
NOTE:	TOUCH UPS REQUIRED THROUGH OUT AS INDICATED		
	INSTALL MIRRORS THROUGHOUT		
FAMILY ROOM			
NOTE:	INSTALL TRIM AT BASE OF FIREPLACE.		
	POT LIGHT BURNT OUT	 	
STAIRS			
NOTE:	PAINT RISERS AT LAUNDRY ROOM. 2ND COAT OF PAINT REQUIRED TO RISERS ON MAIN STAIRS. TOUCH UP STAIN WHERE REQUIRED.	 	
FOYER/HALL			
FLOORING	T-CAP MISSING AT LAUNDRY ROOM.	 	
KITCHEN			
SINK/FAUCET/PLUMBING	INSTALL SINK AND FAUCET.	 	
NOTE:	HOME OWNER NOT EXPECTING EXTENDED BULKHEAD OVER HOOD.	 	
	PURCHASER MAY HAVE PURCHASED FAUX HANDLES TO BE INSTALLED TO FIXED PANELS IN FRONT OF SINK AND COOK TOP	 	
	CHECK BLACK LINE DRAWING FOR LOCATION OF ELECTRIC OUTLET ON ISLAND. PURCHASER ANTICIPATED IT BEING ON THE WEST SIDE OF ISLAND.	 	
EXTERIOR SEASONAL			
PAINT	PAINT LINTELS		
SHARED ENSUITE			
NOTE:	FLUSH MOUNT AIR REGISTER TO FLOOR.	 	
BEDROOM #5			
NOTE:	SHELF MISSING IN CLOSET	 	
MASTER ENSUITE BATH			
NOTE:	DAP AND PAINT BASEBOARD BELOW VANITY COUNTER.		

Enrollment:

Date (YYYY/MM/DD)

2021/07/07

Purchaser Name: Ryan CHANDOO

Stephanie CHANDOO

Phone Res: (647) 225-8021 Phone Bus: (647) 980-3225 Closing Date: June 28, 2021 Inspector: Chris Bergman



Vendor / Builder: 39348

Project: Lormel Developments (Bradford) Ltd

Lot / Phase: 106 / 2 **Plan:** 51M-1087

Address: 255 Chelsea Crescent Municiaplity: Town of Bradford West Gwillimbury

Inspection Date: July 07, 2021

Page 2 of 2

A REFERENCE FOR FUTURE WAR	RANTY REQUESTS.  to designate someone to conduct the PDI in the	E HOME'S CONDITION BEFORE THE PURCHASI neir place should ensure they provide written auth				
I have inspected my new home and I agree that the description of the items listed on this form are accurate.						
Ryan CHANDOO	2	Stephanie CHANDOO				
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature			
		Chris Bergman	CS.			
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature			

July 07, 2021