Enrollment: H2368223

Purchaser Name: Mandip S. DHANOA

Phone: (289) 500-2202

Rajdeep K. DHANOA

Phone: (647) 550-2513
Closing Date: June 24, 2021
Inspector: Chris Bergman



Vendor/Builder No.:

Vendor: Lormel Developments (Bradford) Ltd

Lot/Phase: Part 9, Block 164 / 2A

Address: 307 Chelsea Crescent

Municipality:

Inspection Date: June 16, 2021

Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- · Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

GENERAL COMMENTS		
NOTE:	TOUCH UPS REQUIRED THROUGH OUT AS INDICATED	
	INSTALL MIRRORS IN ALL BATHROOMS	
	CLEAN PAINT DRIPS FROM MAIN FLOOR FLOORING WHERE REQUIRED. TOUCH UP SMALL	
	CHIPS WHERE REQUIRED.	
EXTERIOR SEASONAL		
NOTE:	PAINT LINTELS, GARAGE AND FRONT DOORS	
	CAULK WINDOWS, VENTS, EXHAUST, WATER BIBS AND UTILITY LINES WHERE REQUIRED.	
	REMOVE TAPE FROM WINDOWS WHERE REQUIRED	
	CUSTOMER UNHAPPY WITH LOCATION OF DOWNSPOUT. WANTED TO KNOW IF IT COULD BE	
	RAISED TO THE HEIGHT OF THE SOFFIT.	
BRICKS	CUSTOMER UNHAPPY WITH SMALL CHIPS TO BRICKS AT FRONT DOOR.	
STAIRS		
NOTE:	APPLY CLEAR COAT TO STAIRS	
	CAULK STRINGER TO WALL	
BASEMENT		
WINDOWS	FOUNDATION WINDOW CRACKED	
NOTE:	CUT NAILS FROM WALLS IN COLD ROOM	
UPPER HALL		
FLOORING	TOUCH UP SMALL AREAS NEAR STAIRS AND NAIL HOLE AT ENTRANCE TO 3RD BEDROOM	
BEDROOM 4 ENSUITE		
NOTE:	TOUCH UP GROUT AT LEFT CORNER OF TUB. CAULK BASE OF TUB AT TILE	

Enrollment: H2368223

Purchaser Name: Mandip S. DHANOA

Rajdeep K. DHANOA

 Phone Res:
 (289) 500-2202

 Phone Bus:
 (647) 550-2513

 Closing Date:
 June 24, 2021

 Inspector:
 Chris Bergman



Vendor / Builder:

Project: Lormel Developments (Bradford) Ltd

Lot / Phase: Part 9, Block 164 / 2A

Plan:

Address: 307 Chelsea Crescent

Municiaplity:

Inspection Date: June 16, 2021

Page 2 of 2

KITC	CHEN	
NOT	E:	INSTALL LEVEL 7 BACKSPLASH AS PER UPGRADE
		DRILL HOLE IN COUNTER FOR WATER FILTER AS PER UPGRADE.
		INSTALL VALANCE LIGHTING AS PER PSA
		CHECK SPECIFICATION OF TRIM ABOVE TOP OF CABINETS.
FAM	ILY ROOM	
FLO	ORING	CHIP TO FLOORBOARD
NOT	E:	FIREPLACE MANTEL REQUIRES FINAL COAT OF PAINT.
MAS	STER ENSUITE BATH	
FAU	CETS/PLUMBING	INSTALL UPGRADED FAUCETS AS PER PSA

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Mandip S. DHANOA	Rayloep Laws	Rajdeep K. DHANOA	
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Chris Bergman	3
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2021/06/16	June 16, 2021	