Enrollment:

Purchaser Name: Daylor SLAIWA

Dali SLAIWA

Phone: (416) 566-8748
Phone: (647) 926-1427
Closing Date: June 15, 2021

Inspector: Chris Bergman

Orwel

PDI

Vendor/Builder No.: 39348

Vendor: Lormel Developments (Bradford) Ltd

Lot/Phase: 123 / 2

51M-1087

Address: 187 Chelsea Crescent

Municipality: Town of Bradford West Gwillimbury

Inspection Date: August 11, 2021

Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- · Bathroom accessories if provided
- · Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- · Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

GENERAL COMMENTS		
NOTE:	PAINT TOUCH UPS.	
	INSTALL SCREEN WINDOWS AND WINDOW CRANKS.	
	CLEAN PAINT FROM FLOOR ALONG SHOE OLD WHERE INDICATED	
FOYER/HALL		
NOTE:	DOOR STOPPER MISSING AT DOOR TO BASEMENT	
FLOORING	TOUCH UP FLOORING (3 SPOTS) FROM LAUNDRY ROOM TO LIVING ROOM.	
STAIRS		
NOTE:	APPLY CLEAR COAT.	
TRIM	TRIM NOT FLUSH TO STRINGER. POOR CUTS TO PIECES INSTALLED.	
EXTERIOR SEASONAL		
NOTE:	INSTALL STEPS AT SIDE DOOR.	
	PAINT LENTILS.	
	CAULK VENT AT SIDE OF HOUSE.	
	SOFFIT MISSING AT SIDE OF HOUSE.	
BRICKS	BRICK LOOSE UNDER SOFFIT ON LEFT SIDE OF FRONT PORCH.	
BEDROOM 2 ENSUITE		
SHOWER ENCLOSURE	INSTALL GLASS SHOWER ENCLOSURE	
UPPER HALL		
NOTE:	INSTALL HANDLES TO LINEN CLOSET.	
SHARED ENSUITE		
NOTE:	INSTALL DOOR STOPPER.	
BEDROOM #2		
NOTE:	INSTALL HANDLES TO CLOSET.	

Enrollment:

Date (YYYY/MM/DD)

2021/08/11

Purchaser Name: Daylor SLAIWA

Dali SLAIWA

Phone Res: (416) 566-8748
Phone Bus: (647) 926-1427
Closing Date: June 15, 2021

Inspector: Chris Bergman



PDI

Vendor / Builder: 39348

Project: Lormel Developments (Bradford) Ltd

Lot / Phase: 123 / 2 Plan: 51M-1087

Address: 187 Chelsea Crescent

Municiaplity: Town of Bradford West Gwillimbury
Inspection Date: August 11, 2021

Page 2 of 2

FAMILY ROOM		
NOTE:	INSTALL TRIM AT BASE OF FIREPLACE	
KITCHEN		
CABINETS	DRAWERS WON'T CLOSE.	
BASEMENT		
STAIRS	PAINT STAIRS.	

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. JD-Daylor SLAIWA Dali SLAIWA Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Purchaser's Signature Chris Bergman Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature

August 11, 2021