
FAX TRANSMISSION

To: Pratt Hansen Group Inc.
From: Pratt Homes
Subject: Work order Re: Cheltenham Suites - CHS - 5035 - Newport Interior Wall Systems

Message: Hi Amanda,
Here's the work order you were asking about. Sorry, I missed sending it to you.
This is a model home so you can have assess any time in the next couple of weeks.
Thanks,
Wendy



Pratt Hansen Group
Customer Service
Phone: (705) 792-3883
Fax: (705) 792-3893

Work Order

Address: 15 Cheltenham Rd. Unit 6 - Barrie
Location: Cheltenham Suites - Phase: CHS - Lot: 5035
Today's Date: 14Jul10
Contact Name(s): Model Home
Contact Phone No.: Res: Bus: Bus2: Cell:
Company: Newport Interior Wall Systems
Attention:
Telephone: (705) 737-3111
Fax: (705) 737-9625

Please Complete the following items:

Deficiency Number	Issue		Appt. Date/Time	Notes
2351	Attic- Insulation unevenly distributed in attic. Additional insulation required. OBC 9.25.2.3.			
2352	Attic- Air/vapour barrier was found to be discontinuous at ceiling penetrations at washroom exhaust fan.			
2353	Attic- Gypsum board taping was observed to be poor, missing or not complete in the attic space. OBC 3.1.8.1.(1) & OBC 3.1.8.3.			

Date Completed: _____

Homeowner Signature: _____

Please schedule service to complete the work described above within two weeks of receipt of this Work Order. It is your responsibility to book your own appointment unless we have included appointment details on this form.

Your Service Person must ask the homeowner to sign this form when the work has been completed. If the owner is not available to sign this Work Order, the person who completes the work should sign and date the form. Fax the completed Work Order to us at 705-735-6991.

In the event that you do not complete this service work within 14 days, Pratt Homes reserves the right to carry out the repairs on your behalf and the labour and material costs may be billed back to you plus a 15% administrative fee.

